

Date of Issue :December 20, 2016 FCC ID:2ADA6TLM99S

Report No: C161111R02

IC:12409A-TLM99S

#### **EXTERNAL PHOTOGRAPHS OF EUT**









Report No: C161111R02

Date of Issue :December 20, 2016 FCC ID:2ADA6TLM99S IC:12409A-TLM99S







Date of Issue :December 20, 2016 FCC ID:2ADA6TLM99S

Report No: C161111R02

IC:12409A-TLM99S







Date of Issue :December 20, 2016 FCC ID:2ADA6TLM99S

Report No: C161111R02

IC:12409A-TLM99S

#### TLM99si








Report No: C161111R02

Date of Issue :December 20, 2016 FCC ID:2ADA6TLM99S IC:12409A-TLM99S







Date of Issue :December 20, 2016 FCC ID:2ADA6TLM99S

Report No: C161111R02

IC:12409A-TLM99S



