

Annex B


Radiated Spurious Emissions



Radiated Spurious_1- 5.5 GHz_UHF-HI_450.1025 MHz_NB_p1780015




Radiated Spurious_1- 5.5 GHz_UHF-HI_450.1025 MHz_WB_p1780015




Radiated Spurious_1- 5.5 GHz_UHF-HI_459.9875 MHz_C4FM_p1780015




Radiated Spurious_1- 5.5 GHz_UHF-HI_459.9875 MHz_NB_p1780015




Radiated Spurious_1- 5.5 GHz_UHF-HI_459.9875 MHz_WB_p1780015




Radiated Spurious_1- 5.5 GHz_UHF-HI_469.9875 MHz_C4FM_p1780015




Radiated Spurious_1- 5.5 GHz_UHF-HI_469.9875 MHz_NB_p1780015




Radiated Spurious_1- 5.5 GHz_UHF-HI_469.9875 MHz_WB_p1780015



Radiated Spurious_1- 5.5 GHz_UHF-HI_511.9875 MHz_C4FM_p1780015




Radiated Spurious_1- 5.5 GHz_UHF-HI_511.9875 MHz_NB_p1780015




Radiated Spurious_1- 5.5 GHz_UHF-HI_511.9875 MHz_WB_p1780015




Radiated Spurious_1- 5.5 GHz_UHF-HI_Standby_p1780015




Radiated Spurious_30 - 1000 MHz_UHF-HI_450.1025 MHz_C4FM_p1780015




Radiated Spurious_30 - 1000 MHz_UHF-HI_450.1025 MHz_NB_p1780015




Radiated Spurious_30 - 1000 MHz_UHF-HI_450.1025 MHz_WB_p1780015




Radiated Spurious_30 - 1000 MHz_UHF-HI_459.9875 MHz_C4FM_p1780015




Radiated Spurious_30 - 1000 MHz_UHF-HI_459.9875 MHz_NB_p1780015




Radiated Spurious_30 - 1000 MHz_UHF-HI_459.9875 MHz_WB_p1780015




Radiated Spurious_30 - 1000 MHz_UHF-HI_469.9875 MHz_C4FM_p1780015




Radiated Spurious_30 - 1000 MHz_UHF-HI_469.9875 MHz_NB_p1780015




Radiated Spurious_30 - 1000 MHz_UHF-HI_469.9875 MHz_WB_p1780015




Radiated Spurious_30 - 1000 MHz_UHF-HI_511.9875 MHz_C4FM_p1780015



Radiated Spurious_30 - 1000 MHz_UHF-HI_511.9875 MHz_NB_p1780015



Radiated Spurious_30 - 1000 MHz_UHF-HI_511.9875 MHz_WB_p1780015



Radiated Spurious_30 - 1000 MHz_UHF-HI_Standby_p1780015

