Shenzhen Minew Technologies Co., Ltd

Component list PS1741

Project: MO86SF6.PrjPCB

Revision: V1.1

Report Date: 2017/12/4 14:13:16
Print Date: 05-Dec-17 3:17:03 PM



#	ı Name Error:ERP	LibRef	Comment	Designator	Footprint	Quantity	nn Name Erro
1	414040003	ANTENNA	ANT	A1	ANT-2G4-	1	
2	402150087	CAP	0603,2.2uF	C1, MC10	0603	2	
3	402150063	CAP	0603,100nF	C2	0603	1	
4	402140042	CAP	0402,100nF	C4, C5,C6, MC3, MC19, MC20	0402	6	
5	409020012	LED	1608SURC,普亮红灯	D2	LED0603	1	
6	410020040	SW-PB	5.2*5.2*4.3mm	K1	KS45-A	1	
7	402140023	CAP	0402, 20pF	MC1, MC2	0402	2	
8	402140021	CAP	0402,15pF	MC4, MC5	0402	2	
9	402140030	CAP	0402,100pF	MC7	0402	1	
10	402150088	CAP	0603,1uF	MC9	0603	1	
11	402140055	CAP	0402, 0.8pF	MC11	0402	1	
12	402140020	CAP	0402,12pF	MC14, MC15	0402	2	
13	403150035	INDUCTOR1	0603,10uH	ML1	0603	1	
14	403140029	INDUCTOR1	0402,15nH	ML2	0402	1	
	401130001	RES	0402, 0R	ML3	0402	1	
16	403140028	INDUCTOR1	0402,3.9nH	ML6	0402	1	
17	403140038	INDUCTOR1	0402,6.8nH	ML4	0402	1	
18	408010013	NRF52832	NRF52832-QFAA-48	MU1	QFN6x6-48	1	
19	406010002	MOSFET N	APM2300NG	Q1	SOT-23MOS	1	
20	401130002	RES	0402,10R	R3	0402	1	
21	401130025	RES	0402,100R	R4	0402	1	
22	401130013	RES	0402,100K	R5, R6	0402	2	
23	401130008	RES	0402,10K	R7, R8, R9	C0402	3	
24	419020002	LIS2DH	LIS2DH	U1	LGA2*2-14	1	
25	408180001	PCF85063A	PCF85063A	U2	DFN2626-10	1	
26	407020010	XTAL	32.768K	Y1, Y3	X3215	2	
27	407020009	XTAL2	32MHz (9p ±10ppm 60R)	Y2	3225	1	
Approved				Notes		40	