

Page 1 of 4

Issue Date: 2015-02-18

Test of HBM type T10F S2, T10F S3, T10F S4, T10F S5, T10F S6 to 47 CFR Part 15C, RSS-Gen and RSS-210

ANNEX 4 TO TEST REPORT # EMCC-040197BCA, 2015-02-18

VARIANTS OF T10				
EQUIPMENT UNDER TEST:				
Trade Name: Type Designation(s): Serial Number:	T10 T10F S2, T10F S3, T10F S4, T10F S5, T10F S6 Type S2: Rotor: 150230092, Stator: Test sample, no serial number Type S3: Rotor: 121330133, Stator: Test sample, no serial number Type S4: Rotor: 154630085, Stator: Test sample, no serial number Type S5: Rotor: 180630016, Stator: Test sample, no serial number Type S6: Rotor: 173330052, Stator: Test sample, no serial number			
Equipment Class: Manufacturer: Address: Phone:	Low Power Transceiver Hottinger Baldwin Messtechnik GmbH Im Tiefen See 45 64293 Darmstadt Germany +49 6151 803-681			
Fax: RELEVANT STANDARD(S):	+49 6151 803-98790 47 CFR Part 15C, RSS-210 Issue 8			
MEASUREMENT PROCEDURE:				
⊠ RSS-Gen Issue 4				

CONTENTS		
1	Photos of T10F TYPES	2
2	Internal Photos of T10F ROTOR	2
2	Internal Photos of T105 STATOR	2

EMCCons DR. RAŠEK GmbH & Co. KG Moggast, Boelwiese 8 91320 Ebermannstadt FCC Registration # 878769 Industry Canada Listing # 3464C EMC, Radio, Safety and Environmental Testing Akkreditierungsstelle D-PL-12067-01-00





Issue Date: 2015-02-18

Test of HBM type T10F S2, T10F S3, T10F S4, T10F S5, T10F S6 to 47 CFR Part 15C, RSS-Gen and RSS-210

1 OVERVIEW OF T10F VARIANTS*

	НВМ
Variants FCC-Certification FCC ID: 2ADAT-T10S2TOS6	
IC: 12438A-T10S2TOS6	
HBM: public	


^{*} Overview provided by customer.





Issue Date: 2015-02-18

Test of HBM type T10F S2, T10F S3, T10F S4, T10F S5, T10F S6 to 47 CFR Part 15C, RSS-Gen and RSS-210




^{*} Overview provided by customer.





Issue Date: 2015-02-18

Test of HBM type T10F S2, T10F S3, T10F S4, T10F S5, T10F S6 to 47 CFR Part 15C, RSS-Gen and RSS-210



^{*} Overview provided by customer.