



Issue Date: 2015-02-18

Test of HBM type T10F S2, T10F S3, T10F S4, T10F S5, T10F S6 to 47 CFR Part 15C, RSS-Gen and RSS-210 Part 15C, RSS-Gen And R

## **ANNEX 2 TO TEST REPORT # EMCC-040197BCA, 2015-02-18**

PHOTOGRAPHS OF EUT; EXTERNAL VIEW		
EQUIPMENT UNDER TEST:		
Trade Name: Type Designation(s): Serial Number:	T10F S2, T10F S3, T10F S4, T10F S5, T10F S6 Type S2: Rotor: 150230092, Stator: Test sample, no serial number Type S3: Rotor: 121330133, Stator: Test sample, no serial number Type S4: Rotor: 154630085, Stator: Test sample, no serial number Type S5: Rotor: 180630016, Stator: Test sample, no serial number Type S6: Rotor: 173330052, Stator: Test sample, no serial number	
Equipment Class: Manufacturer: Address:  Phone: Fax:	Low Power Transceiver Hottinger Baldwin Messtechnik GmbH Im Tiefen See 45 64293 Darmstadt Germany +49 6151 803-681 +49 6151 803-98790	
RELEVANT STANDARD(S):	47 CFR Part 15C, RSS-210 Issue 8	
MEASUREMENT PROCEDURE:		
⊠ RSS-Gen Issue 4		

CONTENTS	Page	
1 Photos of T10F TYPES	2	



Issue Date: 2015-02-18

 $Test of \ HBM \ type \ T10F \ S2, \ T10F \ S3, \ T10F \ S4, \ T10F \ S5, \ T10F \ S6 \ to \ 47 \ CFR \ Part \ 15C, \ RSS-Gen \ and \ RSS-210$ 

## 1 PHOTOS OF T10 TYPES



Entire T10F S2



Entire T10F S3



Entire T10F S4



Entire T10F S5



Entire T10F S6

intentionally left blank