

Hottinger Baldwin Messtechnik GmbH

Im Tiefen See 45 D-64293 Darmstadt

Tel. +49 6151 803-0 Fax +49 6151 803-9100

www.hbm.com

Hottinger Baldwin Messtechnik GmbH Im Tiefen See 45 64293 Darmstadt Germany

Federal Communications Commission

7435 Oakland Mills Road

Columbia, MD 21046

07. July 2017

Class II Permissive Change for FCC ID: 2ADAT-T40S0TOS1

We want to add a new variant to the certified torque meter with the FCC ID: 2ADAT-T40S0TOS1

The new variant of the T40S0TOS1 is documented in the test report 040197RA. This type has a new rotor PCB shape, but all electronic parts and the schematics are the same. All other parts are the unchanged.

The external pictures of the stator have not been changed.

The test report 040197RA documents that the new shape of the rotor PCB emits a comparable magnetic and electrical field as the prior certified version.

The new PCB shape has no considerable influence for to the EMC radiation.

Sincerely,

Dr.-Ing. Hans Schuster