

Test of HBM T12 type S3 to 47 CFR 15.225 and RSS-210 Issue 9

ANNEX 2 TO TEST REPORT # EMCC-040197MAB, 2016-09-29

| PHOTOGRAPHS OF EQUIPMENT UNDER TEST (EUT) | | | |
|--|---|--|--|
| EQUIPMENT UNDER TEST: | | | |
| Trade Name: Type Designation(s): Serial Number: Equipment Class: Manufacturer: Address: Phone: Fax: | T12 S3 161030036 (Rotor); none (Stator) Low Power Transceiver Hottinger Baldwin Messtechnik GmbH Im Tiefen See 45 64293 Darmstadt Germany +49 6151 803-681 +49 6151 803-98790 | | |
| RELEVANT STANDARD(S): | 47 CFR 15.225; RSS-210 Issue 9 | | |
| MEASUREMENT PROCEDURE: | | | |
| ⊠ RSS-Gen Issue 4 | | | |


| C | ONTENTS Page | • |
|---|---|---|
| 1 | Internal Photos of T12 TYPE S5: Rotor | 2 |
| 2 | Internal Photos of T12 TYPE S5: Stator4 | Ļ |
| 3 | Internal Photos of T12 TYPE S5: Stator Head | ; |



Issue Date: 2016-09-29

Test of HBM T12 type S3 to 47 CFR 15.225 and RSS-210 Issue 9

1 INTERNAL PHOTOS OF T12 TYPE S3: ROTOR




^{*} Internal pictures provided by customer.

Page 3 of 5

Issue Date: 2016-09-29

Test of HBM T12 type S3 to 47 CFR 15.225 and RSS-210 Issue 9



^{*} Internal pictures provided by customer.



Issue Date: 2016-09-29

Test of HBM T12 type S3 to 47 CFR 15.225 and RSS-210 Issue 9

2 INTERNAL PHOTOS OF T12 TYPE S3: STATOR



Entire EUT, stator installed on a test fixture



All PCBs are covered with a potting component*



Controller PCB front side*



Controller PCB rear side*



Supply - Interface PCB front side*



Supply - Interface PCB rear side*



Issue Date: 2016-09-29

Test of HBM T12 type S3 to 47 CFR 15.225 and RSS-210 Issue 9


3 INTERNAL PHOTOS OF T12 TYPE S3: STATOR HEAD




Entire EUT, stator installed on a test fixture



Bottom view of the stator head*



Stator head PCB front side*



^{*} Internal pictures provided by customer.