

#### Test of HBM T12 type S2 to 47 CFR 15.225 and RSS-210 Issue 9

# **ANNEX 2 TO TEST REPORT # EMCC-040197MAA, 2016-09-29**

PHOTOGRAPHS OF EQUIPMENT UNDER TEST (EUT)			
EQUIPMENT UNDER TEST:			
Trade Name: Type Designation(s): Serial Number: Equipment Class: Manufacturer: Address: Phone:	T12 S2 153030053 (Rotor); none (Stator) Low Power Transceiver Hottinger Baldwin Messtechnik GmbH Im Tiefen See 45 64293 Darmstadt Germany +49 6151 803-0		
Fax:	+49 6151 803-9100		
RELEVANT STANDARD(S):	47 CFR 15.225; RSS-210 Issue 9		
MEASUREMENT PROCEDURE:			
⊠ RSS-Gen Issue 4			

CONTENTS		Page
1	Internal Photos of T12 TYPE S2: Rotor	2
2	Internal Photos of T12 TYPE S2: Stator	4
3	Internal Photos of T12 TYPE S2: Stator Head	5

EMCCons DR. RAŠEK

91320 Ebermannstadt

GmbH & Co. KG

Boelwiese 8




Issue Date: 2016-09-29

## Test of HBM T12 type S2 to 47 CFR 15.225 and RSS-210 Issue 9

## 1 INTERNAL PHOTOS OF T12 TYPE S2: ROTOR



Entire EUT, rotor installed on a test fixture




The rotor includes 4 PCB\*



PCB 1 front side\*



PCB 1 rear side\*



\* Internal pictures provided by customer.






Page 3 of 5

Issue Date: 2016-09-29

## Test of HBM T12 type S2 to 47 CFR 15.225 and RSS-210 Issue 9



<sup>\*</sup> Internal pictures provided by customer.



Issue Date: 2016-09-29

#### Test of HBM T12 type S2 to 47 CFR 15.225 and RSS-210 Issue 9

### 2 INTERNAL PHOTOS OF T12 TYPE S2: STATOR



Entire EUT, stator installed on a test fixture



All PCBs are covered with a potting component\*



Controller PCB front side\*



Controller PCB rear side\*



Supply - Interface PCB front side\*



Supply - Interface PCB rear side\*



Issue Date: 2016-09-29

# Test of HBM T12 type S2 to 47 CFR 15.225 and RSS-210 Issue 9

### **3 INTERNAL PHOTOS OF T12 TYPE S2: STATOR HEAD**




Entire EUT, stator installed on a test fixture



Bottom view of the stator head\*



Stator head PCB front side\*



<sup>\*</sup> Internal pictures provided by customer.