

Test of HBM T12 type S5 to 47 CFR 15.225 and RSS-210 Issue 9

ANNEX 2 TO TEST REPORT # EMCC-040197MAD, 2016-09-29

PHOTOGRAPHS OF EQUIPMENT UNDER TEST (EUT)		
EQUIPMENT UNDER TEST:		
Trade Name: Type Designation(s): Serial Number: Equipment Class: Manufacturer: Address:	T12 S5 201630043 (Rotor); none (Stator) Low Power Transceiver Hottinger Baldwin Messtechnik GmbH Im Tiefen See 45 64293 Darmstadt Germany	
Phone: Fax:	+49 6151 803-681 +49 6151 803-98790	
RELEVANT STANDARD(S):	47 CFR 15.225; RSS-210 Issue 9	
MEASUREMENT PROCEDURE:		
⊠ RSS-Gen Issue 4		

CONTENTS		Page
1	Internal Photos of T12 TYPE S5: Rotor	2
2	Internal Photos of T12 TYPE S5: Stator	4
3	Internal Photos of T12 TYPE S5: Stator Head	5

040197MAD




Issue Date: 2016-09-29

Test of HBM T12 type S5 to 47 CFR 15.225 and RSS-210 Issue 9

1 INTERNAL PHOTOS OF T12 TYPE S5: ROTOR



Entire EUT, rotor installed on a test fixture




The rotor includes 4 PCB*



PCB 1 front side*



PCB 1 rear side*



* Internal pictures provided by customer.




PCB 2 rear side*

Page 3 of 5

Issue Date: 2016-09-29

Test of HBM T12 type S5 to 47 CFR 15.225 and RSS-210 Issue 9



^{*} Internal pictures provided by customer.



Issue Date: 2016-09-29

Test of HBM T12 type S5 to 47 CFR 15.225 and RSS-210 Issue 9

2 INTERNAL PHOTOS OF T12 TYPE S5: STATOR




Entire EUT, stator installed on a test fixture



All PCBs are covered with a potting component*



Controller PCB front side*



Controller PCB rear side*



Supply - Interface PCB front side*



Supply - Interface PCB rear side*



Issue Date: 2016-09-29

Test of HBM T12 type S5 to 47 CFR 15.225 and RSS-210 Issue 9


3 INTERNAL PHOTOS OF T12 TYPE S5: STATOR HEAD




Entire EUT, stator installed on a test fixture



Bottom view of the stator head*



Stator head PCB front side*



Stator head PCB rear side*

^{*} Internal pictures provided by customer.