Test report No. : 11445682H-A-R1 Page : 41 of 42

Issued date : December 19, 2016 FCC ID : 2ADBK-T722A00

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission



Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124


Test report No. : 11445682H-A-R1 Page : 42 of 42


Issued date : December 19, 2016 FCC ID : 2ADBK-T722A00

Worst Case Position

(Horizontal: Y-axis/ Vertical: Z-axis)(Above 1GHz) (Horizontal: X-axis/ Vertical: X-axis)(Below 1GHz)







End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124