

Shenzhen Coosee Technology Co.,LTD.
Room 903,East Block, Chuangxin Technology Plaza II, Tianan Digital City,Futian District,Shenzhen
Tel: 0755-8829 9367 Fax: 0755-8382 0265

## Attestation Letter

September 30, 2014

To: Bay Area Compliance Laboratories Corp. 1274 Anvilwood Avenue Sunnyvale, CA 94089

Louis Denz

Dear Sir or Madam:

The RF chip, model:MT8382, installed in our product MID, model: <u>HV7-CV718, HV7-829</u>, <u>HV7-828, HV7-719, HV7-716, HV7-817</u> which supports EDGE functions. For using in the USA this chip will not support/enable the EDGE function. The EDGE function has been shielded by the manufacturer using the software.

Best Regards,

Sincerely,

Signature:

Lance Deng Quality Director