

page 1 of 8

ANNEX C: INTERNAL PHOTOS



145833_01.JPG: EUT - cabinet backside removed

Test Report No.: F145833E1 3rd Version Order No.: 14-115833 Examiner: Wolfgang KASALOWSKY
Date of issue: 23 March 2015






145833_02.JPG: Mainboard

Test Report No.: F145833E1 3rd Version Order No.: 14-115833 Examiner: Wolfgang KASALOWSKY
Date of issue: 23 March 2015

page 2 of 8





145833_03.JPG: Mainboard

Test Report No.: F145833E1 3rd Version Order No.: 14-115833 Examiner: Wolfgang KASALOWSKY
Date of issue: 23 March 2015

page 3 of 8





145833_04.JPG: CPU board

Examiner: Wolfgang KASALOWSKY
Date of issue: 23 March 2015

Test Report No.: F145833E1 3rd Version Order No.: 14-115833 page 4 of 8





145833_05.JPG: CPU board

Examiner: Wolfgang KASALOWSKY
Date of issue: 23 March 2015

Test Report No.: F145833E1 3rd Version Order No.: 14-115833 page 5 of 8





145833_06.JPG: Cabinet opened and mainboard removed

Test Report No.: F145833E1 3rd Version Order No.: 14-115833 Examiner: Wolfgang KASALOWSKY
Date of issue: 23 March 2015

page 6 of 8




page 7 of 8

ANNEX C: INTERNAL PHOTOS



145833_07.JPG: Monitor backside




145833_19.JPG:Monitor PCB, front side

Test Report No.: F145833E1 3rd Version Order No.: 14-115833 Examiner: Wolfgang KASALOWSKY
Date of issue: 23 March 2015




page 8 of 8

ANNEX C: INTERNAL PHOTOS



145833_08.JPG: Bluetooth module at mainboard



145833_09.JPG: Bluetooth antenna

Test Report No.: F145833E1 3rd Version Order No.: 14-115833 Examiner: Wolfgang KASALOWSKY
Date of issue: 23 March 2015