

Appendix C. Setup Photographs

<Conducted Emission> Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ADHZ-X1000 Page Number : C1 of C4
Report Issued Date : May 05, 2015
Report Version : Rev. 01

Report No.: FR541602B




<Radiated Emission>

X Plane

LF



HF




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ADHZ-X1000 Page Number : C2 of C4
Report Issued Date : May 05, 2015
Report Version : Rev. 01

Report No.: FR541602B



Y Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ADHZ-X1000 Page Number : C3 of C4
Report Issued Date : May 05, 2015
Report Version : Rev. 01


Report No.: FR541602B



Report No.: FR541602B

Z Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ADHZ-X1000 Page Number : C4 of C4
Report Issued Date : May 05, 2015
Report Version : Rev. 01