



DATE August 17, 2015

Federal Communications Commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 20145

To Whom It May Concern:

We request a Class II Permissive Change for our FCC ID: 2ADJKJMA-610.

We have changed the magnetron to an equivalent part; Part Number MAF 1562R.

Antenna conducted testing has been performed and the radar continues to comply with the FCC rules and regulations Part 80.

Sincerely,

A handwritten signature in blue ink that appears to read "Salman".

John Salman
Manager