
Test report No. : 11920648S-D-R1
Page : 36 of 38
Issued date : April 11, 2018
FCC ID : 2ADKK-DTF251

APPENDIX 3: Photographs of test setup

Conducted Emission





UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401


 Test report No.
 : 11920648S-D-R1

 Page
 : 37 of 38

 Issued date
 : April 11, 2018

 FCC ID
 : 2ADKK-DTF251

Radiated Spurious Emission







1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401


Test report No. : 11920648S-D-R1
Page : 38 of 38
Issued date : April 11, 2018
FCC ID : 2ADKK-DTF251

Worst Case Position

X-axis







End of Report

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401