Test report No.
 : 11920654S-A-R2

 Page
 : 30 of 32

 Issued date
 : April 27, 2018

 FCC ID
 : 2ADKK-DTG108

# **APPENDIX 3: Photographs of test setup**

## **Conducted Emission**



Photo 1



Photo 2

UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

 Test report No.
 : 11920654S-A-R2

 Page
 : 31 of 32

 Issued date
 : April 27, 2018

 FCC ID
 : 2ADKK-DTG108

#### **Radiated Spurious Emission**




Photo 1




Photo 2




Photo 3

#### UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

 Test report No.
 : 11920654S-A-R2

 Page
 : 32 of 32

 Issued date
 : April 27, 2018

 FCC ID
 : 2ADKK-DTG108

# **Pre-check of Worst Case Position**







\* 1) Although the color of the above test sample is black, it is a provisional black color because it is a prototype, the specification inside is the same as clear white color of the product version.

## **End of Report**

#### UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401