Test report No.
 : 11920658S-A-R2

 Page
 : 31 of 34

 Issued date
 : April 27, 2018

 FCC ID
 : 2ADKK-DTG114

APPENDIX 3: Photographs of test setup

Conducted Emission

(with AC adapter)



Photo 1



Photo 2

UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

 Test report No.
 : 11920658S-A-R2

 Page
 : 32 of 34

 Issued date
 : April 27, 2018

 FCC ID
 : 2ADKK-DTG114

Conducted Emission

(without AC adapter)




Photo 1



Photo 2

UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

 Test report No.
 : 11920658S-A-R2

 Page
 : 33 of 34

 Issued date
 : April 27, 2018

 FCC ID
 : 2ADKK-DTG114

Radiated Spurious Emission




Photo 1




Photo 2




Photo 3

UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Test report No. : 11920658S-A-R2
Page : 34 of 34
Issued date : April 27, 2018
FCC ID : 2ADKK-DTG114

Pre-check of Worst Case Position







End of Report

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN