Correspondence by Project

Project Number:

-902953787

Correspondence Number	Memo
2ADMLATG-1000-1	1) Please indicate the type of modulation employed by the device. Response: The modulation is GFSK. 2) The block diagram submitted is not sufficient. As per section 2.1033(b)(5) of the FCC rules, the block diagram must show "the frequency of all oscillators used in the device. The signal path and frequency shall be indicated at each block. The tuning range(s) and intermediate frequency(ies) shall be indicated at each block." Response: The block diagram has been revised. 3) The user manual requires the two part FCC statement since the label does not provide it. Please provide an updated user manual. Response: The owners manual has been revised. 4) Please provide a completed TCB contract. A portion of the contract was not completed. Response: The TCB contract has been uploaded. 5) The operational description mentions that 40 channels are used in the device, however the test data shows that only 37 are used. Please provide an updated operational manual. Response: The operational description has been updated to show only 37 channels are used. 6) Please show data showing compliance to the 15.31(e) requirements. Response: The 15.31 (e) exhibit has been uploaded.

1 of 1 12/15/2014 9:54 AM