Report No.: 14110970HKG-002

### **Equipment Photographs**

Model : AB5016(FCC)
AB5016ZT(IC)

(Internal)






Report No.: 14110970HKG-002

## **Equipment Photographs**

Model : AB5016(FCC)
AB5016ZT(IC)

(Internal)





FCC ID: 2ADMY2-4GHZAB5016T

IC: 12572A-4GZAB5016ZT


Report No.: 14110970HKG-002

# **Equipment Photographs**

Model : AB5016(FCC)
AB5016ZT(IC)

(Internal)







Report No.: 14110970HKG-002

# **Equipment Photographs**

Model : AB5016(FCC) AB5016ZT(IC)

(Internal)





FCC ID: 2ADMY2-4GHZAB5016T


IC: 12572A-4GZAB5016ZT


Report No.: 14110970HKG-002

# **Equipment Photographs**

Model : AB5016(FCC) AB5016ZT(IC)

(Internal)





FCC ID: 2ADMY2-4GHZAB5016T


IC: 12572A-4GZAB5016ZT


Report No.: 14110970HKG-002

## **Equipment Photographs**

Model : AB5016(FCC) AB5016ZT(IC)

(Internal)






Report No.: 14110970HKG-002

### **Equipment Photographs**

Model : AB5016(FCC)
AB5016ZT(IC)

(Internal)





Report No.: 14110970HKG-002

# **Equipment Photographs**

Model : AB5016(FCC)
AB5016ZT(IC)

(Internal)



