


# Appendix D. Setup Photographs

# <Conducted Emission>



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ADNC-KA2TB115 Page Number : D1 of D3
Report Issued Date : Jan. 29, 2016
Report Version : Rev. 01

Report No.: FR5O1213E

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.2




Report No. : FR5O1213E


## <Radiated Emission>

### Y Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ADNC-KA2TB115 Page Number : D2 of D3
Report Issued Date : Jan. 29, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.2







Report No.: FR5O1213E

### **Z** Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ADNC-KA2TB115 Page Number : D3 of D3
Report Issued Date : Jan. 29, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.2