

Appendix A. Setup Photographs

<Conducted Emission>



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ADNC-KA2TB115 Page Number : A1 of A2
Report Issued Date : Jan. 29, 2016
Report Version : Rev. 01

Report No.: FR5O1213D

Report Template No.: BU5-FR15CNFC Version 1.0




Report No.: FR5O1213D


<Radiated Emission>

Y Plane

From 9kHz~30MHz



From 30MHz~1GHz



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ADNC-KA2TB115 Page Number : A2 of A2
Report Issued Date : Jan. 29, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CNFC Version 1.0