

Appendix D. Setup Photographs

<Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ADNC-KA2TB115 Page Number : D1 of D2
Report Issued Date : Jan. 29, 2016
Report Version : Rev. 01

Report No.: FR5O1213B


Report Template No.: BU5-FR15CBT4.0 Version 1.2




<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ADNC-KA2TB115 Page Number : D2 of D2
Report Issued Date : Jan. 29, 2016
Report Version : Rev. 01

Report No.: FR5O1213B

Report Template No.: BU5-FR15CBT4.0 Version 1.2