CC Test Report No. : FR4O2012

Appendix A. Test Photos

SPORTON INTERNATIONAL INC. Page No. : A1 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01


FAX: 886-3-327-0973



FCC Test Report No.: FR4O2012

1 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW



REAR VIEW


SPORTON INTERNATIONAL INC. Page No. : A2 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973



FCC Test Report No.: FR4O2012

For radiated emissions 30MHz~1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.
TEL: 886-3-327-3456

FAX: 886-3-327-0973

Page No. : A3 of A5
Report Version : Rev. 01




FCC Test Report Report No. : FR4O2012

For radiated emissions above 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973

Page No. : A4 of A5 : Rev. 01

Report Version






Report No. : FR4O2012

: A5 of A5

: Rev. 01



EUT took a close view



EUT took a close view

SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version

FAX: 886-3-327-0973