

Report No. : FR4N2531

Appendix A. Test Photos

SPORTON INTERNATIONAL INC. Page No. : A1 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01


FAX: 886-3-327-0973






1 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



Report No.: FR4N2531

FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A2 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973




FCC Test Report

Report No. : FR4N2531

For radiated emissions 30MHz~1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973

Page No. : A3 of A4


Report Version : Rev. 01



FCC Test Report

Report No. : FR4N2531

For radiated emissions above 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A4 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973