



Appendix A. Test Photos

1 Photographs of Conducted Emissions Test Configuration



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A1 of A5

Report Version :


: Rev. 01

Report No. : FR4N2531-01





Report No. : FR4N2531-01



SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A2 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01


FAX: 886-3-327-0973






2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



Report No. : FR4N2531-01

FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A3 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01


FAX: 886-3-327-0973




FCC Test Report

Report No. : FR4N2531-01

For radiated emissions 30MHz~1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973

Page No. : A4 of A5
Report Version : Rev. 01




FCC Test Report

Report No. : FR4N2531-01


: A5 of A5

: Rev. 01

For radiated emissions above 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version

FAX: 886-3-327-0973