
3. Internal Photograph of EUT

Brand Name: huaqiang; Model Name: V37

Report No.: EP492307



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ADRZHQ6006AV37 Page Number : 13 of 32
Report Issued Date : Dec. 09, 2014





TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ADRZHQ6006AV37 Page Number : 14 of 32
Report Issued Date : Dec. 09, 2014




Report No.: EP492307



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ADRZHQ6006AV37 Page Number : 15 of 32 Report Issued Date: Dec. 09, 2014



Report No.: EP492307




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ADRZHQ6006AV37

: 16 of 32 Page Number Report Issued Date: Dec. 09, 2014

: Rev. 01

Report Version





SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ADRZHQ6006AV37 Page Number : 17 of 32

Report Issued Date: Dec. 09, 2014



Brand Name: huaqiang; Model Name: V37

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ADRZHQ6006AV37 Page Number : 18 of 32
Report Issued Date : Dec. 09, 2014
Report Version : Rev. 01



Report No.: EP492307




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ADRZHQ6006AV37 Page Number : 19 of 32

Report Issued Date: Dec. 09, 2014 Report Version : Rev. 01



Report No.: EP492307



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ADRZHQ6006AV37 Page Number : 20 of 32

Report Issued Date: Dec. 09, 2014




Report No.: EP492307



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ADRZHQ6006AV37 Page Number : 21 of 32 Report Issued Date: Dec. 09, 2014



Report No.: EP492307



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ADRZHQ6006AV37 Page Number : 22 of 32


Report Issued Date: Dec. 09, 2014

Report No.: EP492307



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ADRZHQ6006AV37 Page Number : 23 of 32
Report Issued Date : Dec. 09, 2014







TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ADRZHQ6006AV37 Page Number : 24 of 32
Report Issued Date : Dec. 09, 2014

Report Issued Date: Dec. 09, Report Version: Rev. 01






TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ADRZHQ6006AV37 Page Number : 25 of 32
Report Issued Date : Dec. 09, 2014
Report Version : Rev. 01




SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ADRZHQ6006AV37 Page Number : 26 of 32
Report Issued Date : Dec. 09, 2014
Report Version : Rev. 01



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ADRZHQ6006AV37 Page Number : 27 of 32
Report Issued Date : Dec. 09, 2014
Report Version : Rev. 01




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ADRZHQ6006AV37 Page Number : 28 of 32
Report Issued Date : Dec. 09, 2014
Report Version : Rev. 01



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ADRZHQ6006AV37 Page Number : 29 of 32
Report Issued Date : Dec. 09, 2014

Report No.: EP492307



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ADRZHQ6006AV37 Page Number : 30 of 32
Report Issued Date : Dec. 09, 2014

Report No.: EP492307

GPS Antenna < Rx>

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ADRZHQ6006AV37 Page Number : 31 of 32
Report Issued Date : Dec. 09, 2014
Report Version : Rev. 01



Report No.: EP492307



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ADRZHQ6006AV37 Page Number : 32 of 32

Report Issued Date: Dec. 09, 2014 Report Version : Rev. 01