|          | BOM                  |   |  |      |
|----------|----------------------|---|--|------|
| NO.      | Model                | Description   | Local  | Unit |
|          |                      | MD  |  |      |
| 9000018A | P-JS-29G11           |   |  |      |
| 9000018B | AR-80106-002         | antenna shrapnel;H=0.5-<br>0.9mm  | ANT301, ANT302, ANT303,<br>ANT1201, ANT1202, ANT1203,<br>ANT1204 | 7    |
| 9000018C | 81800A081            |   | ANT 1204   |      |
| 8500067A | 02-032113u-A         |   |  |      |
| 8500067D | BA-1501-001          | 3Pin Battery Connector, H=1.5mm  BAT1001  1.7mm micro-sim+T-FLASH 3in1 SIM Card trestle  CON801 | BAT1001  | 1    |
| 8500067E | PAN30-03154-S100     |   |  |      |
| 8200065A | HMSM003-17A120       |   | CON801   | 1    |
| 9000032A | 818000904            | antenna shrapnel;H=1.25mm   | CON901, CON902   | 2    |
| 8300153A | 24 5804 030 000 829+ | D(II)   | COVIDED COVIDED COVIDED  | 0    |
| 8300153C | 0K-22NF030-04        | BTB, connector, H=0.9, 30pin CON90  | CON903, CON904, CON905   | 3    |
| 8310021A | US-2415-001          | E ' MICDO HCD H 1 C   | COMITOR  | 1    |
| 8310021B | UAF95-05164-S13001   | 5pin MICRO-USB, H=1.6mm   | CON1001  | 1    |
| 8300147A | 24-5804-010-000-829+ | D000  | COMPANA  |      |
| 8300147C | 0K-22NF010-04        | BTB, connector, H=0.9, 10pin  | CON1002  | 1    |
| 8300173A | 504618-2010          | 0.6mm, 0.35PITCH, 20PIN BTB SOCKET  | CON1003  | 1    |
| 8300132A | FH34S-6S-0. 5SH(50)  |   |  |      |
| 8300132B | AYF530635HS1         |   |  |      |
| 8300132C | FPC0517-06R-TAG      | ZIF, 6PIN, H=1mm, 0. 5pitch, co   | COMMONA  |      |
| 8300132D | XF2W-0615-1A         | nnector.  | CON1004  | 1    |
| 8300132E | ECF051006GLB-3       |   |  |      |
| 8300132F | 818002390            |   |  |      |
| 8100007A | ECT818000531         | RF connector, H=1.3mm   | SW301  | 1    |
| 8100008A | ECT818000291         | RF connector, H=1.0mm   | SW302, SW303   | 2    |
| 9000023A | TP80203-001          | SHIELDING clamp, H=0.8  | SH1, SH2, SH3, SH4, SH5, SH6                                     | 6    |

|          | <u> </u>                 | COOO DE CHIENENIA CERCI   |  |    |
|----------|--------------------------|---|--|----|
| 9400368A | C228-RF-FRAME-SHIELDING  | C228-RF-SHIELDING, C7521,<br>T=0.2  | SH101  | 1  |
| 9400369A | C228-PMU-SHIELDING       | C228 PMU-SHIELDING,<br>C7521, T=0.2   | SH601  | 1  |
| 9400222A | C218-FLASH-SHIELDING     | C228 LED-SHIELDING,   | SH901  | 1  |
| 9400222E | C218-FLASH-SHIELDING     | C7521, T=0.2  | 20301  | 1  |
| 9400215A | C218-WIFI-GPS-SHIELDING  | C228 GPS-3in1-SHIELDING,  | CHIOOI   | 4  |
| 9400215E | C218-WIFI-GPS-SHIELDING  | C7521, T=0.2  | SH1201   | 1  |
| 9400216A | C218-GPS-RF-SHIELDING    | C228 GPS-RF-SHIELDING,  | CHIOAO   | 1  |
| 9400216E | C218-GPS-RF-SHIELDING    | C7521, T=0.2  | SH1202   | 1  |
| 9400370A | C228-BB-SHEILDING        | C228-BB-SHIELDING,<br>SUS304, T=0.2   |  | 1  |
| 9400371A | C228-RF-SHIELDING-COVER  | C228 RF-SHIELDING,<br>SUS304, T=0.2   |  | 1  |
| 9700651A | C228 PCB V1. 1           | C228 PCB, 0.8mm, 4in1, 65*52.2*0.8,   |  | 1  |
| 8320017A | NJP453-102T              | 3.5mm Earphone jack,  | Ј1101  | 1  |
| 8320017B | JAF00-05132-0153         | H=3. 6mm  | J1101  | 1  |
|          |                          | IC  |  |    |
| 4300022B | SS0840WS                 | Dealers battanes v2 0mm   | D001   | 1  |
| 4300022D | PSBD3D40V1H              | Backup battery,ø3.8mm   | D901   | 1  |
| 6170022A | ICMF062P900 (ICT)        |   |  |    |
| 6170022B | ACFT4A2G900E(Amotech)    |   | E901, E902, E903, E904, E905                                   |    |
| 6170022C | TCF03025H90002A(Inpaq)   | EMI Filter<br>90R@100MHz, 0.85mm*0.65mm   | , E906, E907, E908, E909, E91<br>0, E911, E912, E913, E914, E9 | 15 |
| 6170022D | EXC14CE900U(panasonic)   |   | 15   |    |
| 6170022E | MCZ0806AH900L2TAOG (TDK) |   |  |    |
| 4330004A | WNM4002-3/TR(Will)       | Mosfet, N-ch, 1.6*1.6,<br>Vgs=1.8V, Id=300mA  | Q501   | 1  |
| 4330006A | NTLUS3A18PZTAG           | Mosfet, P-ch, 2. 0x2. 0x0. 55, Id MAX=-8.2 A  | Q1001  | 1  |
| 7100019A | MT6169V/A                | GSM/EDGE/WCDMA/HSPA+/TD-<br>SCDMA/FDD-LTE/TDD-LTE RF<br>Transceiver, TFBGA, 6.2*5.4*<br>0.9,0.4 pitch, 175 ball | U228   | 1  |
| 7310009A | MT6328V/A                | PMU IC  | U701   | 1  |
| 6120060A | KXTJ2-1009               | LowG Sensor, 2mm*2mm  | U803   | 1  |
|          |                          |   |  |    |

| 6160071A | MMC35240PJ           | 3-axis Magnetic Sensor  | U805    | 1  |
|----------|----------------------|---|---------|----|
| 4110010A | SN3232I310E          |   |         |    |
| 4110010B | SGM3141YD10G/TR      | 1.0A Buck/Boost Charge  |         |    |
| 4110010C | CP2158DN10-A1        | Pump LED Driver   | U901    | 1  |
| 4110010D | ET9381               | 1   |         |    |
| 4110007A | RT8514GJ6(TichIek)   |   |         |    |
| 4110007B | ET5120(Etek)         | LOW D. TO DO /DO  | 11000   |    |
| 4110007C | APW7209CI(Anpec)     | LCM Driver IC DC/DC   | U902    | 1  |
| 4110007D | uP6003AMT6(uPiSemi)  | ]   |         |    |
| 4100011A | AS2930M5-2.8/TR-LF   |   |         |    |
| 4100011B | LC1463CB5ATR28       | ]   |         |    |
| 4100011C | RP1202-28GB          | 2.8V, 300mA, LDO  | U903    | 1  |
| 4100011D | PT7M8202B28TA5EX     |   |         |    |
| 4100011E | ME6211C28M5G         |   |         |    |
| 4130009A | NCP1851AFCCT1G       | 1.6A Charge IC  | U1001   | 1  |
| 6140010A | SN2010B              | CLASS-D 1.68W(8Ω-5V)<br>Audio Power Amplifier   | U1101   | 1  |
| 6160067A | APM-12D23-20-DF8/TR8 | O' 1 ALCADO C   | U1100   | -1 |
| 6160067B | AP3426               | ─3in1 ALS&PS Sensor   | U1102   | 1  |
| 6110025A | OCH165TWAD           | Unipolar Hall Sensor IC   | U1103   | 1  |
| 7600017A | MT6625LN/A           | GPS/WIFI/BT/FM WIFI   | U1201   | 1  |
| 5200071A | RDALN16-PH1          |   |         |    |
| 5200071B | AR8159-S85UDG        | LNA, 1575. 42MHz,   | 111 202 | 1  |
| 5200071D | MXDLN16G             | 1.5*1.0*0.72,6pin QFN;Gain 18.5dB,NOISE 0.75dB  | 01203   | 1  |
| 5200071E | AW5005DNR            |   |         |    |
| 5210014A | RSFP2402D            | FBAR, BLUETOOTH/WLAN<br>FILTER, UNBALANCE-UNBALANCE<br>50欧姆, 1411, PASS<br>BAND=79.0MHz, F0=2441.0MHz | U1204   | 1  |
| 5200600A | RFDIP160806BLM5T62   | DIPLEXER, WIFI (BT) 2. 4GHz/WI<br>FI5. 8GHz , 1608,<br>Hmax=0.7mm, MT6625L                            | U1205   | 1  |

| 5200640A             | B8813   | GNSS (GPS/GALILEO/GLONASS/C                            |  | 1  |
|----------------------|---|--|--|----|
| 5200641A             | SAFFB1G56KB0F0A   |  | U1206  |    |
| 5200642A             | F6QA1G581M2QZ   | 1602MHz, 1109, 50-<br>50, Hmax=0. 5mm                  |  |    |
| 5150027A             | KT2520K26000ZAW28QAS<br>(KY0CERA)                                       |  |  |    |
| 5150027B             | DSA221SDN(1XXA26000MAA)<br>(KDS)  | VCTCXO, 26MHz FOR<br>MT6162/MT6169, 2520, 2.8V,        |  |    |
| 5150027C             | ENG3349A  | Stability 0.5ppm, Tolerance                            | X101   | 1  |
| 5150027D             | 7L26001018 (S3) (TXC)   | 2ppm, 10pF, 10Kohm,<br>Vcon=1.4±1.0V, Hmax=0.9mm       |  |    |
| 5150027J             | TG-5006CG-10W<br>(X1G0042110034) (EPSON)<br>1TJF125DP1A000A (DTS310) (K | vcon=1.4±1.0v, Hmax=0.9mm                              |  |    |
| 6130003A<br>6130003B | DS) FC-135 12. 5pF (EPSON)  |  |  |    |
| 6130003C             | ST3215SB32768H5HPWAA (KYOC  | 32.768KHz Crystal, SIZE<br>3215,<br>OSC 12.5pF, ±20ppm |  |    |
| 6130003D             | ERA)<br>XTL721-S999-286 (SX-<br>3215) (SIWARD)                          |  |  |    |
| 6130003E             | TFX-02CL1205001 (RIVER)   |  | X701   |    |
| 6130003F             | NX3215SA (STD-MUA-4 (NDK)   |  |  | 1  |
| 6130003G             | 9Н03200031  |  |  |    |
| 6130003Н             | FC-135  |  |  |    |
| 6130003I             | CM315D  |  |  |    |
| 6130003J             | TFX-02SCL125-J21123   |  |  |    |
| 6130003K             | SC-32S  |  |  |    |
| 4310001A             | PZ5D4V2H  | Zener Diode  | ZD1001   | 1  |
| 7200159A             | MT6735V/WP  | 1G, 4-core, LTE FDD 5M, BB&AP, HD,8MP                  | U602   | 1  |
| 1)64+8               | 3   |  |  |    |
| 6100200A             | KMQ7X000SA-B315   |  |  |    |
| 6100200B             | KMQ72000SM-B316   | 64Gb+8Gb eMMC+LPDDR3                                   | U801   | 1  |
| 6100200C             | SD9DS28K-8G   |  |  |    |
|                      |   | RCL  |  |    |
| 1000001A             | WRO2X000PAL (WALSIN)  |  | R704, R801, R802, R804, R805                             |    |
| 1000001B             | RC0201JR-070RL (YAGE0)  | RES, $0R \pm 5\%$ , $1/20\%$ , $0201$                  | , R819, R1108, R1201, R1205,<br>LCR1202, LCR1203, R1203, | 14 |

| 10000010 | R0201JXX0000P20LTZ (EYANG) |   | C739, C740   |   |
|----------|----------------------------|---|--------------|---|
|          | WR06X000PTL (WALSIN)       |   |              |   |
|          | RC0603JR-070RL (YAGEO)     | RES, 0R±5%, 1/16W, 0603                   | R606         | 1 |
|          |                            | RES, UK <u>1</u> 5%, 1/10%, 0003          | ROOO         | 1 |
|          | R0603JXX0000P10LTS (EYANG) |   |              |   |
|          | RL1206FR-070R01L (YAGEO)   | RES, 0. 01R±1%, 1/4W, 1206                | R1012        | 1 |
|          | R1206WXXR010F04LTC (EYANG) |   |              |   |
|          | WW08XR068FTL (WALSIN)      |   |              |   |
| 1140009B | RL0805FR-7W0R068L (YAGEO)  | RES, 0. $068R \pm 1\%$ , $1/4\%$ , $0805$ | R1003        | 1 |
| 1140009C | R0805WXXR068F08LTB (EYANG) |   |              |   |
| 1120007A | WW06XR300FTL (WALSIN)      |   |              |   |
| 1120007B | RL0603FR-070R3L (YAGEO)    | RES, 0. $3R \pm 1\%$ , $1/10\%$ , $0603$  | R901         | 1 |
| 1120007C | R0603WXXR30XF10LTS (EYANG) |   |              |   |
| 1000011B | RC0201JR-071RL (EYANG)     | RES, 1R±5%, 1/20W, 0201                   | R705         | 1 |
| 1000011C | R0201RXX1R0XJ20LHZ (EYANG) | REG, TR <u>-</u> 5%, 1/20%, 0201          | K100         | 1 |
| 1100146A | WRO4X8R2JTL(WALSIN)        |   |              |   |
| 1100146B | RC0402JR-078R2 (YAGE0)     | RES, 8. $2R \pm 5\%$ , $1/16\%$ , $0402$  | R905, R910   | 2 |
| 1100146C | R0402RXX8R2XJ16LTA (EYANG) |   |              |   |
| 1000031A | WRO2X330JAL(WALSIN)        |   |              |   |
| 1000031B | RC0201JR-0733RL (YAGEO)    | RES, 33R±5%, 1/20W, 0201                  | R702, R703   | 2 |
| 1000031C | R0201RXX330XJ20LTZ (EYANG) |   |              |   |
| 1000035A | WRO2X360JAL (WALSIN)       |   |              |   |
| 1000035B | RC0201JR-0736RL (YAGEO)    | RES, 36R±5%, 1/20W, 0201                  | R513         | 1 |
| 1000035C | R0201RXX360XJ20LTZ (EYANG) |   |              |   |
| 1000056B | RC0201FR-07240RL (YAGE0)   |   |              |   |
| 1000056C | R0201RXX241XF20LTZ (EYANG) | RES, 240R $\pm$ 1%, 1/20W, 0201           | R807, R809   | 2 |
| 1000058B | RC0201JR-07470RL (YAGEO)   |   |              |   |
| 1000058C | WRO2X471 JAL               | RES, 470R±5%, 1/20W, 0201                 | R1115, R1116 | 2 |
|          | WRO2X102JAL (WALSIN)       |   |              |   |

| 1000061B | RC0201JR-071KL (YAGEO)     | RES, 1K±5%, 1/20W, 0201                           | R708, R1017, R1114                        | 3 |
|----------|----------------------------|---|---|---|
| 1000061C | R0201RXX102XJ20LTZ (EYANG) |   |   |   |
| 1000066A | WRO2X1501FAL(WALSIN)       | PPG 1 5W   10/1 / / / / / / / / / / / / / / / / / | DE-14 DE00                                | 0 |
| 1000066B | RC0201FR-071K5             | RES, 1. 5K $\pm$ 1%, 1/20W, 0201                  | R514, R706                                | 2 |
| 1100014A | WRO4X152JTL(WALSIN)        |   |   |   |
| 1100014B | RC0402JR-071K5L (YAGE0)    | RES, 1. 5K $\pm$ 5%, 1/16W, 0402                  | R1001                                     | 1 |
| 1100014C | R0402RXX152XJ16LTA (EYANG) |   |   |   |
| 1000079A | WR02X2491FAL (WALSIN)      | DEC 0 40V   10/ 1/90W 0901                        | D1100                                     | 1 |
| 1000079B | RC0201FR-072K49L (YAGE0)   | RES, 2. 49K $\pm$ 1%, 1/20W, 0201                 | R1120                                     | 1 |
| 1100017A | WR04X332JTL(WALSIN)        |   |   |   |
| 1100017B | RC0402JR-073K3L (YAGEO)    | RES, 3. $3K \pm 5\%$ , $1/16W$ , $0402$           | B1112                                     | 1 |
| 1100017C | R0402RXX332XJ16LTA (EYANG) |   |   |   |
| 1000081A | WR02X472JAL (WALSIN)       |   | DEGO DEGO DEGA DEGE DEGO                  |   |
| 1000081B | RC0201JR-074K7L (YAGE0)    | RES, 4. 7K $\pm$ 5%, 1/20W, 0201                  | R502, R503, R504, R505, R506<br>,<br>R507 | 6 |
| 1000081C | R0201RXX472XJ20LTZ (EYANG) |   | roor                                      |   |
| 1000175A | WR02X5101FAL (WALSIN)      |   |   |   |
| 1000175B | RC0201FR-075K1L (YAGE0)    | RES, 5. 1K $\pm$ 1%, 1/20W, 0201                  | R501                                      | 1 |
| 1000175C | R0201RXX512XF20LTZ (EYANG) |   |   |   |
| 1100100A | WR04X8201FTL(WALSIN)       |   |   |   |
| 1100100B | RC0402FR-078K2L (YAGE0)    | RES, 8. $2K \pm 1\%$ , $1/16W$ , $0402$           | R511, R512                                | 2 |
| 1100100C | R0402RXX822XF16LTA (EYANG) |   |   |   |
| 1000091A | WRO2X103JAL(WALSIN)        |   |   |   |
| 1000091B | RC0201JR-0710KL (YAGEO)    | RES, 10K±5%, 1/20W, 0201                          | R903, R909, R911, R1103,<br>R1121         | 5 |
| 1000091C | R0201RXX103XJ20LTZ (EYANG) |   |   |   |
| 1100156A | WRO4X3902FTL(WALSIN)       |   |   |   |
| 1100156B | RC0402FR-0739KL (YAGE0)    | RES, $39K \pm 1\%$ , $1/16W$ , $0402$             | R1004                                     | 1 |
| 1100156C | R0402RXX393XF16LTA (EYANG) |   |   |   |
| 1000121A | WRO2X473 (WALSIN)          |   |   |   |

| 1000121B | RC0201JR-0747KL (YAGEO)    | RES, 47K±5%, 1/20W, 0201                             | R515, R1113, R1118, R1119                               | 4  |
|----------|----------------------------|--|---|----|
| 1000121C | R0201RXX473XJ20LTZ (EYANG) |  |   |    |
| 1100126A | WRO4X563JTL (WALSIN)       |  |   |    |
| 1100126B | RC0402JR-0756KL (YAGEO)    | RES, 56K±5%, 1/16W, 0402                             | R902  | 1  |
| 1100126C | R0402RXX563XJ16LTA (EYANG) |  |   |    |
| 1000124B | RC0201FR-0761K9L (YAGEO)   | RES, 61. 9K±1%, 1/20W, 0201                          | R1011   | 1  |
| 1000131A | WRO2X104JAL (WALSIN)       |  |   |    |
| 1000131B | RC0201JR-07100KL (YAGEO)   | RES, 100K±5%, 1/20W, 0201                            | R811, R814, R904, R906,<br>R1005, R1008, R1010          | 7  |
| 1000131C | R0201RXX104XJ20LTZ (EYANG) |  |   |    |
| 1400007A | NTCG104EF104FTIX           | NTC, 100K±5%, 1/16W, 0402                            | NTC801  | 1  |
| 1000139B | RC0201FR-07200KL (YAGEO)   |  |   |    |
| 1000139C | R0201RXX204XJ20LTZ (EYANG) | RES, $200\text{K} \pm 5\%$ , $1/20\text{W}$ , $0201$ | R701  | 1  |
| 1100159A | WRO4X3303FTL (WALSIN)      |  |   |    |
| 1100159B | RC0402FR-07330KL (YAGEO)   | RES, 330K±1%, 1/16W, 0402                            | R1002   | 1  |
| 1100159C | R0402RXX334XF16LTA (EYANG) |  |   |    |
| 1100160A | WRO4X3903FTL (WALSIN)      |  |   |    |
| 1100160B | RC0402FR-07390KL (YAGEO)   | RES, $390$ K $\pm 1$ %, $1/16$ W, $0402$             | R816  | 1  |
| 1100160C | R0402RXX394XF16LTA (EYANG) |  |   |    |
| 1000151A | WRO2X474JAL (WALSIN)       |  |   |    |
| 1000151B | RC0201JR-07470KL (YAGEO)   | RES, 470K±5%, 1/20W, 0201                            | R1112   | 1  |
| 1000151C | R0201RXX474XJ20LTZ (EYANG) |  |   |    |
| 2000080C | CM03CG180J50AH(AVX)        |  |   |    |
| 2000080F | CC0201JRNP09BN180 (YAGE0)  | CAP, 18pF±5%, 50V, 0201                              | C734, C735, C1211, C1201, C1202                         | 5  |
| 2000080G | C0201C0G180J500NTA (EYANG) |  |   |    |
| 2000090C | CM03CG330J50AH(AVX)        |  |   |    |
| 2000090F | CC0201 JRNP09BN330 (YAGE0) | CAP, 33pF±5%, 50V, 0201                              | C1016, C1017, C1102, C1103, C1107, C1108, C1118, C1119, | 11 |
| 2000090G | C0201C0G330J500NTA (EYANG) |  | C1120, C1121, C1203                                     |    |
| 2000140C | CM03X7R101K25AH (AVX)      |  |   |    |

| 2000140F | CC0201JRNP08BN101 (YAGE0)       | CAP, 100pF±10%, 25V, 0201  | C1015, C1104, C1206, C1117, C1213 | 5 |
|----------|---------------------------------|----------------------------|-----------------------------------|---|
| 2000140G | C0201X7R101K250NTA (EYANG)      |                            |                                   |   |
| 2000170C | CM03X7R102K25AH(AVX)            |                            |                                   |   |
| 2000170F | CC0201KRX7R8BB102 (YAGEO)       | CAP, 1nF±10%, 25V, 0201    | C741                              | 1 |
| 2000170G | C0201X7R102K250NTA (EYANG)      |                            |                                   |   |
| 2100016A | GRM155R71H102KA01D(muRata)      |                            |                                   |   |
| 2100016B | C1005X7R1H102KT (TDK)           |                            |                                   |   |
| 2100016C | CM05X5R102K50AH (AVX)           |                            |                                   |   |
| 2100016D | CL05B102KB5NNNC (SAMSUNG)       | CAP, 1nF±10%, 50V, 0402    | C908                              | 1 |
| 2100016E | 0402B102K500CT (WALSIN)         |                            |                                   |   |
| 2100016F | CC0402KRX7R9BB102 (YAGEO)       |                            |                                   |   |
| 2100016G | C0402X7R102K500NTB (EYANG)      |                            |                                   |   |
| 2000175C | CM03X5R472K10AH(AVX)            |                            |                                   |   |
| 2000175F | CC0201KRX7R6BB472 (YAGEO)       | CAP, 4. 7nF±10%, 10V, 0201 | C1207                             | 1 |
| 2000175G | C0201X7R472K100NTA (EYANG)      |                            |                                   |   |
| 2000180C | CM03X5R103K10AH(AVX)            |                            |                                   |   |
| 2000180F | CC0201KRX7R6BB103 (YAGE0)       | CAP, 10nF±10%, 10V, 0201   | C1214, C1215                      | 2 |
| 2000180G | C0201X5R103K100NTA (EYANG)      |                            |                                   |   |
| 2120035A | GRM188R71H103KA61D(muRata)      | CAP, 10nF±5%, 50V, 0603    | C1003                             |   |
| 2120035B | C1608X7R1H103KT (TDK)           |                            |                                   |   |
| 2120035C | CM105X7R103K50AT (AVX)          |                            |                                   |   |
| 2120035D | CC0603JRNP09BN103(SAMSUNG)      |                            |                                   | 1 |
| 2120035E | 0603N103J500CT(walsin)          |                            |                                   | 1 |
| 2120035F | CC0603KRX7R9BB103 (YAGEO)       |                            |                                   |   |
| 2120035G | C0603X5R103K500NTD (EYANG)      |                            |                                   |   |
| 2120035Н | UMK107CH103JW-<br>F(TaiyoYuden) |                            |                                   |   |
| 2000001A | GRM033R60J104KE19D(muRata)      |                            | C501, C502, C503, C504, C505      |   |
| 2000001B | CC0201X5R0J104KT00NN(TDK)       |                            | C506, C625, C636, C637, C640      |   |

| 2000001C | CM03X5R104K06AH (AVX)         |                              | ,  |    |
|----------|-------------------------------|------------------------------|--|----|
| 2000001F | CC0201KRX5R5BB104 (YAGE0)     | CAP, 100nF±10%, 6. 3V, 0201  | C650, C653, C654, C655, C659   | 53 |
| 2000001G | C0201X5R104K6R3NTA (EYANG)    |                              | C660, C661, C662, C663, C664<br>,<br>C720, C722, C724, C736, C802<br>, C804, C807, C810, C813, C81<br>4 C815 C816 C822 C823 C8 |    |
| 2000184B | CC0201MRX5R5BB224             | CAD 000 B   00% C 0V 0001    | C665, C666, C803, C1109,   | 1  |
| 2000184C | CO2O1X5R224M6R3NTJ            | CAP, 220nF±20%, 6. 3V, 0201  | C1124  | 5  |
| 2000190A | GRM033R60J105MEA2D(muRata     |                              | C507, C607, C609, C611, C613   |    |
| 2000190B | C0603X5R0J105MT00NE (TDK)     |                              | C615, C617, C618, C619, C620   |    |
| 2000190D | CL03A105MQ3CSNH               |                              | C621, C622, C623, C624, C629   |    |
| 2000190E | CVO3X5R105M06AH(WALSIN)       | CAP, 1uF±20%, 6. 3V, 0201    | C630, C631, C632, C651, C702   | 53 |
| 2000190F | CC0201MRX5R5BB105 (YAGE0)     |                              | C703, C704, C705, C706, C710   |    |
|          | CO201X5R105M6R3NTX (EYANG)    |                              | C718, C719, C723, C730, C731   |    |
|          | CV03X5R105M06AH (KYOCRA)      |                              | C732, C733, C737, C738, C742   |    |
| 2100043A | GRM155R60J105KE19D (muRata    |                              | C801, C809, C818, C819, C821   |    |
|          | )<br>C1005X5R0J105KT000F(TDK) |                              |  |    |
|          |                               |                              |  |    |
|          | CM05X5R105K06AH (AVX)         |                              |  |    |
|          | CL05A105KQ5NNNC (SAMSUNG)     | CAP, 1uF±10%, 6. 3V, 0402    | C909   | 1  |
| 2100043E | 0402X105K6R3CT (WALSIN)       |                              |  |    |
| 2100043F | CC0402KRX5R5BB105 (YAGE0)     |                              |  |    |
| 2100043G | CO402X5R105K6R3NTB (EYANG)    |                              |  |    |
| 2100043Ј | ECJ0EB0J105K (PANASONIC)      |                              |  |    |
| 2120042D | CL10A105KB8NNNC (SAMSUNG)     | CAP, 1uF±10%, 50V, 0603      | C907   | 1  |
| 2120042G | C0603X5R105M500NTD (EYANG)    | Chi, Tui = 10%, 807, 0000    |  | 1  |
| 2100084A | GRM155R60J225ME87D(muRata)    |                              | C645, C657, C658, C701, C707   |    |
| 2100084B | C1005X5R0J225MTJ00F(TDK)      |                              | C708, C711, C713, C714, C715   |    |
| 2100084C | CV05X5R225M06AH (AVX)         | CAP, 2. 2uF±20%, 6. 3V, 0402 | C716, C717, C726, C727, C745   | 29 |
| 2100084F | CC0402MRX5R5BB225 (YAGEO)     |                              | C808, C811, C812, C915, C917   |    |
| 2100084G | CO4O2X5R225M6R3NTB (EYANG)    |                              | C920, C921, C923, C928, C930   |    |
|          | , =:=/                        |                              | C933, C1005, C1014, C1020  |    |

|          | GRM155R60J475ME87D(muRata  |  |                                   |    |
|----------|----------------------------|--|-----------------------------------|----|
| 2100085A | )                          |  | C605, C606, C614, C616, C633      |    |
| 2100085B | C1005X5R0J475MTJ00F(TDK)   |  | ,<br>C634, C647, C652, C725, C728 |    |
| 2100085C | CV05X5R475M06AH065 (AVX)   | CAP, 4. 7uF±20%, 6. 3V, 0402                 | ,<br>C729, C805, C806, C817, C825 | 25 |
| 2100085D | CL05A475MQ5NRNC (SAMSUNG)  | Oni, 1. Tur <u>- 20%</u> , 0. 51, 0102       | ,<br>C906, C912, C913, C922, C925 | 20 |
| 2100085F | CC0402MRX5R5BB475 (YAGEO)  |  | ,<br>C1002, C1008, C1106, C1115,  |    |
| 2100085G | CO4O2X5R475M6R3NTC (EYANG) |  | C1210                             |    |
| 2120036A | GRM188R60J106ME47D(muRata) |  |                                   |    |
| 2120036D | CL10A106MQ8NNNC2 (SAMSUNG) |  |                                   |    |
| 2120036F | CC0603MRX5R5BB106 (YAGE0)  | CAP, 10uF±20%, 6. 3V, 0603,<br>H=1mm         | C712, C904, C910, C1006           | 4  |
| 2120036G | C0603X5R106M6R3NTK (EYANG) |  |                                   |    |
| 2120036I | CV105X5R106M06AT (KYCORA)  |  |                                   |    |
| 2120037A | GRM188R60J226MEAOD(muRata) |  |                                   |    |
| 2120037B | C1608X5R0J226MT000E(TDK)   |  | C602, C603, C604, C612, C626      | 11 |
| 2120037D | CL10A226MQ8NRNC1 (SAMSUNG) | CAP, 22uF±20%, 6. 3V, 0603,<br>H=1mm         | ,<br>C627, C628, C709, C721, C902 |    |
| 2120037F | CC0603MRX5R5BB226 (YAGE0)  |  | ,<br>C1004                        |    |
| 2120037G | C0603X5R226M6R3NRK (EYANG) |  |                                   |    |
| 2140060C | C0805X5R476N6R3NTY         | CAP, 47uF±                                   | CC01 CC00 CC10                    | 3  |
| 2140060D | CL21A476MQCLRNC (SAMSUNG)  | 30%, 6. 3V, 0805, H0. 85mm                   | C601, C608, C610                  | 3  |
| 2300014A | TCTAL0J107M8R              | TAN, 100uF±20%, 6.3V, 1206(3216), Hmax=1.2mm | 61011                             | 1  |
| 2300014B | F920J107MAALZT             | TAN, 100uF±20%, 6.3V, 1206(3216), Hmax=1.2mm | -C1011                            | 1  |
| 3030042B | MHQ0603W6N2ST000           |  |                                   |    |
| 3030042D | SDCL0603Q6N2ST02           |  |                                   |    |
| 3030042E | CHQ0603T-6N2C-HU           | IND, 6. 2nH± 0. 3nH, 300mA, SRF=4. 0GHz,     | L1202                             | 1  |
| 3030042F | TFL0603T-6N2J-S            | Q=13@500MHz, 0201                            |                                   |    |
| 3030042G | MGCI0603T6N2ST-LF          |  |                                   |    |
| 3030044B | MHQ0603W7N5JT000           |  |                                   |    |
| 3030044D | SDCL0603Q7N5JT02           | IND G 5 H                                    |                                   |    |
| 3030044E | CHQ0603T-7N5H-HU           | IND, 7. 5nH± 5%, 250mA, SRF=3. 8GHz,         | L1201                             | 1  |

| 3030044F | TFL0603T-7N5JS-S                 | ♥ <sup>−</sup> 10%000mmz, 0201  |                           |   |
|----------|----------------------------------|---|---------------------------|---|
| 3030044G | MGCI0603T7N5JT-LF                |   |                           |   |
| 3030061B | MHQ0603W39NJT000                 |   |                           |   |
| 3030061D | SDCL0603Q39NJT02                 | IND, 39nH±  |                           |   |
| 3030061E | CHQ0603T-39NJ-HU                 | 5%, 160mA, SRF=1. 6GHz,<br>Q=13@500MHz, 0201  | L1207, L1209              | 2 |
| 3030061G | MGCI0603T39NJT-LF                |   |                           |   |
| 3030068D | SDCL0603Q82NJT02                 |   |                           |   |
| 3030068E | CHQ0603T-82NJ-HU                 | 5%, 70mA, SRF=1.1GHz,   | L1210                     | 1 |
| 3030068G | MGCI0603T82NJT-LF                | Q=11@300MHz, 0201   |                           |   |
| 3410008C | MPIA252010-R33M-LF               | IND, 0. 33uH±   |                           |   |
| 3410008D | WPN252010HR33MT                  | 20%, 5A, 2. 5*2. 0,<br>H: 1-1. 2mm  | L701                      | 1 |
| 3410009C | MPIA201610-R47M-LF               | IND, 0. 47uH±   | 1500 1500 1501            | 0 |
| 3410009D | WPN201610HR47MT                  | 30%, 3A, 2. 0*1. 6,<br>H: 1-1. 2mm  | L702, L703, L704          | 3 |
| 3410011B | MPIE201610-2R2M-LF               |   |                           |   |
| 3410011C | VLS201610HBX-2R2                 | 20%, 1. 5A, 2. 0*1. 6,  | L705                      | 1 |
| 3410011D | WPN201610H2R2MT                  | 5%, 160mA, SRF=1. 6GHz, Q=13@500MHz, 0201  IND, 82. 0nH± 5%, 70mA, SRF=1. 1GHz, L1210  IND, 0. 33uH± 20%, 5A, 2. 5*2. 0, H:1-1. 2mm  IND, 0. 47uH± 30%, 3A, 2. 0*1. 6, H:1-1. 2mm  IND, 2. 2uH± 20%, 1. 5A, 2. 0*1. 6, H:1-1. 2mm  L705   |                           |   |
| 3410012G | WIP252010P-2R2ML(Inpaq,侧焊盘)      |   | L1001                     | 1 |
|          | LQH3NPN220MG0 (murata)           |   |                           |   |
| 3220024B | VLS3010ET-220M(TDK)              |   |                           |   |
| 3220024C | MPIL3010-220M-<br>LF(MicroGate)  | IND, 22uH±  | 1001                      | 1 |
| 3220024D | SWPA3010S220MT(Sunlord)          |   | L901                      | 1 |
| 3220024E | LVS303010-220M-<br>N(Chilisin)   |   |                           |   |
| 3220024F | NR3010T220M(TAIY0)               |   |                           |   |
| 3300007A | BLM15BD182SN1D(muRata)           |   |                           |   |
| 3300007C | MGGB1005M182HT-LF<br>(MICROGATE) | Bead, 0402, 1.8K@100MHz,  | B703, B704, B1003, B1107, |   |
| 3300007D | HZ1005K182TFB03(Sunlord)         | 5%, 160mA, SRF=1. 6GHz, Q=13@500MHz, 0201  IND, 82. 0nH± 5%, 70mA, SRF=1. 1GHz, Q=11@300MHz, 0201  IND, 0. 33uH± 20%, 5A, 2. 5*2. 0, H:1-1. 2mm  IND, 0. 47uH± 30%, 3A, 2. 0*1. 6, H:1-1. 2mm  IND, 2. 2uH± 20%, 1. 5A, 2. 0*1. 6, H:1-1. 2mm  IND, 2. 2uH± 20%, 2A, 2. 5*2, H:1mm  IND, 2. 2uH± 20%, 2A, 3. 5*2, H:1mm |                           | 8 |
| 3300007E | SZ1005K182CTF(Sunlord)           |   |                           |   |
| 3300002A | BLM15BB750SN1D(MURATA)           |   |                           |   |

|          |                                 | LTE                             |  |    |
|----------|---------------------------------|---------------------------------|--|----|
| 1000001C | R0201JXX0000P20LTZ (EYANG)      |                                 |  |    |
| 1000001B | RC0201JR-070RL (YAGE0)          | RES, 0R±5%, 1/20W, 0201         | R808, R810   | 2  |
| 1000001A | WRO2XOOOPAL (WALSIN)            |                                 |  |    |
| 4310002E | PESDWC2FD5VB(Prisemi)           |                                 |  |    |
| 4310002D | PESD5V0U1BL (NXP)               |                                 |  |    |
| 4310002C | PJSD05U30LCFN2(PanJit)          | Bi-TVS, 0402, 5V, 1pF-3pF       | V1002, V1003, V1109, V1111   | 4  |
| 4310002B | CMTLDF02C1R8AFE(Cybermax)       |                                 |  |    |
| 4310002A | ESD9B5VL-2/TR(Will)             |                                 |  |    |
| 1300016E | PESDNC2FD5VB                    |                                 |  |    |
| 1300016D | PJSD05LCFN2                     | Bi_TVS, 0402, 5V, 20pF-35pF V1  | V1101, V1102, V1107, V1108,<br>V1110   |    |
| 1300016C | ESD9B5V-2/TR                    |                                 | V1014, V1015, V1017, V1020, V1021, V1022, V1023, V1024, V1 | 17 |
| 1300016B | uClampO511P                     |                                 | V1001, V1010, V1012, V1013,  |    |
| 1300016A | PESD5V0S1BL                     | V                               | V1016, V1019   |    |
| 1300010E | SDV1005S180C030YPTF(Sunlord)    |                                 |  |    |
| 1300010D | SFI0402-120E100NP-LF(SFI)       |                                 | V1004, V1005, V1006, V1007,<br>V1008, V1009, V1011, V1016,<br>V1018, V1019   |    |
| 1300010C | ICVL0518100Y500FR (ICT)         | VAR, 18VDC, 10pF, 0402          | V806, V901, V902, V903, V904   | 20 |
| 1300010B | AVLC18S02003 (AMOTECH)          | ,                               | V801, V802, V803, V804, V805   |    |
| 1300010A | B72590T8140S160 (EPCOS)         |                                 |  |    |
| 3310002E | PBY160808T-221Y-N(chilisin      |                                 |  |    |
| 3310002D | PZ1608U221-1R4TF(Sunlord)       | Bead, 220R, 100MHz, 0603, DCR=0 | B901, B1103, B1104   | 3  |
| 3310002C | MGLB1608M221T1R4-LF(MicroG      |                                 |  |    |
| 3310002A | BLM18PG221SN1D(muRata)          |                                 |  |    |
| 3300002E | NBQ100505T-750Y-<br>N(CHILISIN) |                                 |  |    |
| 3300002D | SZ1005G750TF(Sunlord)           | Bead, 75R/68R, 100MHz, 0402     | B1105, B1106, B1111, B1201   | 8  |
| 3300002C | MGSB1005A750T-LF<br>(MICROGATE) | D1 7FD/COD 100ML 0400           | B1001, B1002, B1101, B1102,  | 0  |

| 5120070A | SKY77643-11                   | MMMB PA, FDD BAND1/3//7/20, WCDMA 1/2/5/8 ; CH BWmax=20MHz, MIPI, APT, 4*6.8 *0.8mm, 42PAD | U105   | 1  |
|----------|-------------------------------|--|--|----|
| 2000085C | CM03CG220J50AH(AVX)           |  |  |    |
| 2000085F | CC0201 JRNP09BN220 (YAGE0)    | CAP, 22pF±5%, 50V, 0201  | C307   | 1  |
| 2000085G | C0201C0G220J500NTA (EYANG)    |  |  |    |
| 1000001A | WRO2X000PAL (WALSIN)          |  |  |    |
| 1000001B | RC0201JR-070RL (YAGEO)        | RES, 0R±5%, 1/20W, 0201  | R307, L301, LCR307, LCR306,<br>LCR301, R308, R121, R114, | 11 |
| 1000001C | R0201JXX0000P20LTZ (EYANG)    |  | R102, R115, R132   |    |
| 1000045A | WRO2X620JAL (WALSIN)          |  |  |    |
| 1000045B | RC0201JR-0762RL (YAGEO)       | RES, 62R±5%, 1/20W, 0201   | R304   | 1  |
| 1000045C | R0201RXX620XJ20LTZ (EYANG)    |  |  |    |
| 1000046A | WRO2X1050FAL (WALSIN)         |  |  |    |
| 1000046B | RC0201JR-07105RL (YAGEO)      | RES, 105R±1%, 1/20W, 0201  | R305, R306   | 2  |
| 1000046C | R0201RXX1050F20LTZ (EYANG)    |  |  |    |
| 1000061A | WRO2X102JAL (WALSIN)          |  |  |    |
| 1000061B | RC0201JR-071KL (YAGEO)        | RES, 1K±5%, 1/20W, 0201  | R111, R112   | 2  |
| 1000061C | R0201RXX102XJ20LTZ (EYANG)    |  |  |    |
| 1000075A | WRO2X2001FAL (WALSIN)         |  |  |    |
| 1000075B | RC0201FR-072KL (YAGEO)        | RES, $2K \pm 1\%$ , $1/20W$ , $0201$   | R110   | 1  |
| 1000075C | R0201RXX202XF20LTZ<br>(EYANG) |  |  |    |
| 1000091A | WR02X103JAL (WALSIN)          |  |  |    |
| 1000091B | RC0201JR-0710KL (YAGE0)       | RES, 10K±5%, 1/20W, 0201   | R301   | 1  |
| 1000091C | R0201RXX103XJ20LTZ (EYANG)    |  |  |    |
| 1000111A | WRO2X243JAL (WALSIN)          |  |  |    |
| 1000111B | RC0201JR-0724KL (YAGE0)       | RES, 24K±5%, 1/20W, 0201   | R303   | 1  |
| 1000111C | R0201RXX243XJ20LTZ (EYANG)    |  |  |    |
| 1400005A | NTCG064EF104FT                | NTC, 100K±1%, 1/20W, 0201  | NTC101   | 1  |

|          |                            | 1   | 1          |   |
|----------|----------------------------|---|------------|---|
| 1100023A | WRO4X104JTL(WALSIN)        |   |            |   |
| 1100023B | RC0402JR-07100KL (YAGEO)   | RES, $100K \pm 5\%$ , $1/16W$ , $0402$                        | R106       | 1 |
| 1100023C | R0402RXX104XJ16LTA (EYANG) |   |            |   |
| 1000148B | RC0201FR-07390KL           | RES, 390K±1%, 1/20W, 0201                                     | R113       | 1 |
| 1000148C | R0201RXX394XF20LTZ         | RES, 390K ± 1%, 1/20w, 0201                                   | K113       | 1 |
| 3010022D | SDCL0603Q2N7BT02           |   |            |   |
| 3010022E | CHQ0603T-2N7B-HU           | IND, 2. 7nH±<br>0. 1nH, 290mA, SRF=9. 2GHz,                   | L106       | 1 |
| 3010022F | TFL0603T-2N7B-S            | Q=13@500MHz, 0201   | L100       | 1 |
| 3010022G | MGCI0603T2N7BT-LF          |   |            |   |
| 3030039B | MHQ0603W4N7ST000           |   |            |   |
| 3030039D | SDCL0603Q4N7ST02           | IND, 4.7nH±<br>0.3nH, 350mA, SRF=5.5GHz,<br>Q=13@500MHz, 0201 |            |   |
| 3030039E | CHQ0603T-4N7C-HU           |   | L113       | 1 |
| 3030039F | TFL0603T-4N7J-S            |   |            |   |
| 3030039G | MGCI0603T4N7ST-LF          |   |            |   |
| 3030046B | MHQ0603W9N1JT000           |   |            |   |
| 3030046D | SDCL0603Q9N1JT02           | IND 0 15H4  |            |   |
| 3030046E | CHQ0603T-9N1H-HU           | IND, 9. 1nH±<br>5%, 250mA, SRF=3. 8GHz,<br>Q=13@500MHz, 0201  | L305, L116 | 2 |
| 3030046F | TFL0603T-9N1J-S            | Q-13@3000m12, 0201  |            |   |
| 3030046G | MGCI0603T9N1JT-LF          |   |            |   |
| 3030061B | MHQ0603W39NJT000           |   |            |   |
| 3030061D | SDCL0603Q39NJT02           | IND, 39nH±<br>5%, 160mA, SRF=1.6GHz,                          | L304, L309 | 2 |
| 3030061E | CHQ0603T-39NJ-HU           | Q=13@500MHz, 0201   | 1304, 1309 | 4 |
| 3030061G | MGCI0603T39NJT-LF          |   |            |   |
| 2000011F | CC0201CRNP09BN1R2 (YAGE0)  | CAD 1 2nF±0 25nF 50V 0201                                     | C118, C119 | 2 |
| 2000011G | CO201COG1R2C500NTA (EYANG) | CAP, 1. $2pF \pm 0$ . $25pF$ , $50V$ , $0201$                 | 0110, 0113 | 4 |
| 2000060C | CM03CG8R2J50AH(AVX)        |   |            |   |
| 2000060F | CC0201CRNP09BN8R2 (YAGE0)  | CAP, 8. 2pF±0. 5pF, 50V, 0201                                 | C117       | 1 |
| 2000060G | C0201C0G8R2C500NTA (EYANG) |   |            |   |

| 2000070C | CM03CG100J50AH (AVX)       |                             |   |    |
|----------|----------------------------|-----------------------------|---|----|
|          | CC0201 JRNP09BN100 (YAGEO) | CAP, 10pF±5%, 50V, 0201     | C303  | 1  |
|          | C0201C0G100J500NTA (EYANG) | , , – , ,                   |   |    |
|          | CM03CG220,J50AH (AVX)      |                             |   |    |
|          | CC0201 JRNP09BN220 (YAGE0) | CAP, 22pF±5%, 50V, 0201     | C316  | 1  |
|          | C0201C0G220J500NTA (EYANG) |                             |   |    |
|          | CM03CG330J50AH (AVX)       |                             |   |    |
|          | CC0201 JRNP09BN330 (YAGE0) | CAP, 33pF±5%, 50V, 0201     | C143, C306, C308, C312, C150                              | 5  |
|          | C0201C0G330J500NTA (EYANG) |                             |   |    |
|          | CM03X7R101K25AH (AVX)      |                             |   |    |
|          | CC0201JRNP08BN101 (YAGE0)  | CAP, 100pF±10%, 25V, 0201   | C111  | 1  |
|          | C0201X7R101K250NTA (EYANG) |                             |   |    |
|          | CM03X7R102K25AH (AVX)      |                             |   |    |
|          | CC0201KRX7R8BB102 (YAGE0)  | CAP, 1nF±10%, 25V, 0201     | C302, C137  | 2  |
|          | C0201X7R102K250NTA (EYANG) | CAF, THE ± 10%, 25V, 0201   |   |    |
| 2000180C | CMO3X5R103K10AH (AVX)      |                             |   |    |
| 2000180F | CC0201KRX7R6BB103 (YAGE0)  | CAP, 10nF±10%, 10V, 0201    | C305  | 1  |
| 2000180G | C0201X5R103K100NTA (EYANG) |                             |   |    |
| 2000001A | GRM033R60J104KE19D(muRata  |                             |   |    |
| 2000001B | CC0201X5R0J104KT00NN (TDK) |                             |   |    |
| 2000001C | CM03X5R104K06AH (AVX)      | CAP, 100nF±10%, 6. 3V, 0201 | C105, C107, C109, C112, C124, C125, C126, C127, C128, C12 | 14 |
| 2000001F | CC0201KRX5R5BB104 (YAGE0)  |                             | 9, C130, C138, C162, C161                                 |    |
|          | C0201X5R104K6R3NTA (EYANG) |                             |   |    |
|          | CC0201MRX5R5BB474 (YAGE0)  |                             |   |    |
|          | CO201X5R474M6R3NTJ (EYANG) | CAP, 470nF±20%, 6. 3V, 0201 | C102  | 1  |
|          | CM03CG180J50AH (AVX)       |                             |   |    |
| 2000080F | CC0201JRNP09BN180 (YAGE0)  | CAP, 18pF±5%, 50V, 0201     | C309, C310, C311  | 3  |
|          | C0201C0G180J500NTA (EYANG) |                             |   |    |

| 2000190A | GRM033R60J105MEA2D(muRata) |   |                        |   |
|----------|----------------------------|---|------------------------|---|
| 2000190B | C0603X5R0J105MT00NE(TDK)   |   |                        |   |
| 2000190D | CL03A105MQ3CSNH            |   |                        |   |
| 2000190E | CV03X5R105M06AH(WALSIN)    | CAP, $1 \text{uF} \pm 20\%$ , 6. 3V, 0201                                   | C101, C106, C108, C110 | 4 |
| 2000190F | CC0201MRX5R5BB105 (YAGE0)  |   |                        |   |
| 2000190G | CO201X5R105M6R3NTX (EYANG) |   |                        |   |
| 20001901 | CV03X5R105M06AH(KY0CRA)    |   |                        |   |
| 2100084A | GRM155R60J225ME87D(muRata) |   |                        |   |
| 2100084B | C1005X5R0J225MTJ00F(TDK)   | CAP, 2. 2uF ± 20%, 6. 3V, 0402  |                        |   |
| 2100084C | CV05X5R225M06AH (AVX)      |   | C123                   | 1 |
| 2100084F | CC0402MRX5R5BB225 (YAGE0)  |   |                        |   |
| 2100084G | CO4O2X5R225M6R3NTB (EYANG) |   |                        |   |
| 2120037A | GRM188R60J226MEAOD(muRata) |   | C304                   |   |
| 2120037B | C1608X5R0J226MT000E(TDK)   |   |                        |   |
| 2120037D | CL10A226MQ8NRNC1 (SAMSUNG) | CAP, 22uF ± 20%, 6. 3V, 0603,<br>H=1mm                                      |                        | 1 |
| 2120037F | CC0603MRX5R5BB226 (YAGE0)  |   |                        |   |
| 2120037G | C0603X5R226M6R3NRK (EYANG) |   |                        |   |
| 3M_B1    | +3+7+20                    |   |                        |   |
| 5120080B | SKY77910-11                | SP10T TRX FEM, GSM<br>QBAND, GPRS/EDGE, , MIPI, 5. 5*<br>5. 3*0. 8mm, 38PAD | U301                   | 1 |
| 5300091A | RDASW41                    | SP4T, 0. 1–3. 0GHz, IL=0. 39–dB, ISO>30dB, QFN14                            |                        |   |
| 5300092A | RTC8614                    | 2. 0*2. 0*0. 75mm,<br>PINmax=37. 5dBm, GPIO, VDD=2.<br>5-5. 0V              | U303                   | 1 |
| 5200140A | SAYFH1G74CA0B0A            | SAW-DUPLEX, WCDMA/LTE Band<br>3, BAL RX, 2016, 50-100                       | U214                   | 1 |
| 5200170A | PJ D6HN2G655BN56           | SAW-DUPLEX, LTE Band 7,   | U222                   | 1 |
| 5200170B | PJ D6HN2G655BN54           | BAL RX, 2016, 50-100  | 0222                   | 1 |
| 5200210A | SAYFH806MCA0F0A            | SAW-DUPLEX, LTE Band 20,<br>BAL RX, 2016, 50-100                            | U201                   | 1 |
| 5200390A | SAFFB806MFA0F0A            | RX SAW, WCDMA/LTE BAND<br>20, BAL, 1109, 50-100                             | U207                   | 1 |
| 5200320A | SAFFB1G84FL0F0A            | RX SAW, WCDMA/LTE BAND<br>3, BAL, 1109, 50-100                              | U213                   | 1 |
|          |                            |   |                        |   |

| 5200301A | F6QG2G140P2KA-J            | RX SAW, WCDMA/LTE BANDand 1/4, BAL, 1109, 50-100     | U215             | 1 |
|----------|----------------------------|--|------------------|---|
| 5200342A | SAFFB2G65FB0F0A            | RX SAW, WCDMA/LTE BAND 7, BAL, 1109, 50-100          | U218             | 1 |
| 1000131A | WRO2X104JAL (WALSIN)       |  |                  |   |
| 1000131B | RC0201JR-07100KL (YAGEO)   | RES, $100\text{K} \pm 5\%$ , $1/20\text{W}$ , $0201$ | R104, R107, R108 | 3 |
| 1000131C | R0201RXX104XJ20LTZ (EYANG) |  |                  |   |
| 1100113A | WR04X474JTL (WALSIN)       |  |                  |   |
| 1100113B | RC0402JR-07470KL (YAGEO)   | RES, $470$ K $\pm$ 5%, $1/16$ W, $0402$              | R105             | 1 |
| 1100113C | R0402RXX474XJ16LTA (EYANG) |  |                  |   |
| 3010005D | SDCL0603Q1N0BT02           |  |                  |   |
| 3010005E | CHQ0603T-1N0B-HU           | IND, 1. 0nH±   | C220             | 1 |
| 3010005F | TFL0603T-1N0B-S            | 0. 1nH, 520mA, SRF=10GHz,<br>Q=13@500MHz, 0201       | C238             | 1 |
| 3010005G | MGCI0603T1N0BT-LF          |  |                  |   |
| 3010010D | SDCL0603Q1N5BT02           |  |                  |   |
| 3010010E | CHQ0603T-1N5B-HU           | IND, 1. 5nH±   | 1117 (000 1051   | 0 |
| 3010010F | TFL0603T-1N5B-S            | 0. 1nH, 410mA, SRF=10GHz,<br>Q=13@500MHz, 0201       | L117, C222, L251 | 3 |
| 3010010G | MGCI0603T1N5BT-LF          |  |                  |   |
| 3010013D | SDCL0603Q1N8BT02           |  |                  |   |
| 3010013E | CHQ0603T-1N8B-HU           | IND, 1. 8nH±   | 1,000            | 1 |
| 3010013F | TFL0603T-1N8B-S            | 0. 1nH, 380mA, SRF=10GHz,<br>Q=13@500MHz, 0201       | L263             | 1 |
| 3010013G | MGCI0603T1N8BT-LF          |  |                  |   |
| 3010017D | SDCL0603Q2N2BT02           |  |                  |   |
| 3010017E | CHQ0603T-2N2B-HU           | IND, 2. 2nH±   | C201             | 1 |
| 3010017F | TFL0603T-2N2B-S            | 0. 1nH, 290mA, SRF=10GHz,<br>Q=13@500MHz, 0201       | C201             | 1 |
| 3010017G | MGCI0603T2N2BT-LF          |  |                  |   |
| 3010019D | SDCL0603Q2N4BT02           |  |                  |   |
| 3010019E | CHQ0603T-2N4B-HU           | IND, 2. 4nH±   | 1110 1040 1005   |   |
| 3010019F | TFL0603T-2N4B-S            | 0. 1nH, 290mA, SRF=10GHz,<br>Q=13@500MHz, 0201       | L119, L242, L265 | 3 |
| 3010019G | MGCI0603T2N4BT-LF          | ]  |                  |   |

| 3010022D | SDCL0603Q2N7BT02  |  |                  |   |
|----------|-------------------|--|------------------|---|
|          | CHQ0603T-2N7B-HU  |  |                  |   |
| 3010022F | TFL0603T-2N7B-S   | 0. 1nH, 290mA, SRF=9. 2GHz,<br>Q=13@500MHz, 0201   | L239             | 1 |
| 3010022G | MGCI0603T2N7BT-LF |  |                  |   |
| 3010025D | SDCL0603Q3N0BT02  |  |                  |   |
| 3010025E | CHQ0603T-3N0B-HU  | IND, 3. 0nH±   |                  |   |
| 3010025F | TFL0603T-3N0B-S   | -0. 1nH, 280mA, SRF=8. 6GHz,<br>Q=13@500MHz, 0201  | L245             | 1 |
| 3010025G | MGCI0603T3N0BT-LF |  |                  |   |
| 3010028D | SDCL0603Q3N3BT02  |  |                  |   |
| 3010028E | CHQ0603T-3N3B-HU  | IND, 3.3nH±  | 1,000 1,115      | 0 |
| 3010028F | TFL0603T-3N3B-S   | -0. 1nH, 270mA, SRF=8. 1GHz,<br>Q=13@500MHz, 0201  | L230, L115       | 2 |
| 3010028G | MGCI0603T3N3BT-LF |  |                  |   |
| 3030039B | MHQ0603W4N7ST000  |  | L240, L274, L236 |   |
| 3030039D | SDCL0603Q4N7ST02  |  |                  |   |
| 3030039E | CHQ0603T-4N7C-HU  |  |                  | 3 |
| 3030039F | TFL0603T-4N7J-S   | →Q=13@500MHz, 0201   |                  |   |
| 3030039G | MGCI0603T4N7ST-LF |  |                  |   |
| 3030041B | MHQ0603W5N6ST000  |  |                  |   |
| 3030041D | SDCL0603Q5N6ST02  | TND F C.H.   | L234, L252, L214 |   |
| 3030041E | CHQ0603T-5N6C-HU  | <ul> <li>IND, 5. 6nH±</li> <li>0. 3nH, 350mA, SRF=5. 0GHz,</li> <li>Q=13@500MHz, 0201</li> </ul> |                  | 3 |
| 3030041F | TFL0603T-5N6J-S   | Q=13@300MHz, 0201  |                  |   |
| 3030041G | MGCI0603T5N6ST-LF |  |                  |   |
| 3030042B | MHQ0603W6N2ST000  |  |                  |   |
| 3030042D | SDCL0603Q6N2ST02  | - IND, 6. 2nH±   |                  |   |
| 3030042E | CHQ0603T-6N2C-HU  | 0. 3nH, 300mA, SRF=4. 0GHz,<br>—Q=13@500MHz, 0201  | L223, L219, L227 | 3 |
| 3030042F | TFL0603T-6N2J-S   | 4 100000min, 0201  |                  |   |
| 3030042G | MGCI0603T6N2ST-LF |  |                  |   |
| 3030046B | MHQ0603W9N1JT000  |  |                  |   |

| 3030046D | SDCL0603Q9N1JT02           |   |                  |   |
|----------|----------------------------|---|------------------|---|
| 3030046E | CHQ0603T-9N1H-HU           | IND, 9. 1nH±<br>5%, 250mA, SRF=3. 8GHz,                   | C153, C203       | 2 |
| 3030046F | TFL0603T-9N1J-S            | -Q=13@500MHz, 0201  |                  |   |
| 3030046G | MGCI0603T9N1JT-LF          |   |                  |   |
| 3030051B | MHQ0603W15NJT000           |   |                  |   |
| 3030051D | SDCL0603Q15NJT02           |   |                  |   |
| 3030051E | CHQ0603T-15NH-HU           | IND, 15nH±<br>5%, 180mA, SRF=2.8GHz,<br>Q=13@500MHz, 0201 | L220             | 1 |
| 3030051F | TFL0603T-15NJ-S            | -Q-13@300MHZ, 0201  |                  |   |
| 3030051G | MGCI0603T15NJT-LF          |   |                  |   |
| 3030053B | MHQ0603W18NJT000           |   |                  |   |
| 3030053D | SDCL0603Q18NJT02           | IND 10 H  |                  |   |
| 3030053E | CHQ0603T-18NH-HU           | IND, 18nH±<br>5%, 180mA, SRF=2. 4GHz,                     | L241, L215, L203 | 3 |
| 3030053F | TFL0603T-18NJ-S            | -Q=13@500MHz, 0201  |                  |   |
| 3030053G | MGCI0603T18NJT-LF          |   |                  |   |
| 3030055B | MHQ0603W22NJT000           |   |                  |   |
| 3030055D | SDCL0603Q22NJT02B          | IND 00 H  |                  |   |
| 3030055E | CHQ0603T-22NH-HU           | IND, 22nH±<br>5%, 160mA, SRF=2. 2GHz,                     | L213             | 1 |
| 3030055F | TFL0603T-22NJ-S            | Q=13@500MHz, 0201   |                  |   |
| 3030055G | MGCI0603T22NJT-LF          |   |                  |   |
| 2000010C | CM03CGR50C50AH (AVX)       |   |                  |   |
| 2000010F | CC0201CRNP09BNR50 (YAGE0)  | CAP, 0. $5pF \pm 0$ . $25pF$ , $50V$ , $0201$             | C157, C160       | 2 |
| 2000010G | C0201C0G0R5C500NTA (EYANG) |   |                  |   |
| 2000012C | CM03CG1R8C50AH (AVX)       |   |                  |   |
| 2000012E | 0201N1R8C500CT (WALSIN)    | CAD 1 0mp. LO 05 p 50V 0001                               | CIEA             | 1 |
| 2000012F | CC0201CRNP09BN1R8 (YAGE0)  | CAP, 1. $8pF \pm 0$ . $25pF$ , $50V$ , $0201$             | U154             | 1 |
| 2000012G | C0201C0G1R8C500NTA (EYANG) |   |                  |   |
| 2000021F | CC0201CRNP09BN2R2 (YAGE0)  | CAD O OUD LO OF D FOU OCCU                                | C010, C01C       | 0 |
| 2000021G | C0201C0G2R2C500NTA (EYANG) | CAP, 2. $2pF \pm 0$ . $25pF$ , $50V$ , $0201$             | (219, 6216       | 2 |

| 2000022C | CMO3CG2R7C5OAH (AVX)       |   |  |   |
|----------|----------------------------|---|--|---|
| 2000022E | 0201N2R7C500CT (WALSIN)    |   |  |   |
| 2000022F | CC0201CRNP09BN2R7 (YAGE0)  | CAP, 2. $7pF \pm 0$ . $25pF$ , $50V$ , $0201$ | C254, C262                                     | 2 |
| 2000022G | C0201C0G2R7C500NTA (EYANG) |   |  |   |
| 2000031C | CM03CG3R3C50AH (AVX)       |   |  |   |
| 2000031E | 0201N3R3C500CT (WALSIN)    |   |  |   |
| 2000031F | CC0201CRNP09BN3R3 (YAGE0)  | CAP, 3. 3pF±0. 25pF, 50V, 0201                | L243, L249, C267, C271, C243, C245, L201, L204 | 8 |
| 2000031G | C0201C0G3R3C500NTA (EYANG) |   | ,,   |   |
| 2000032G | C0201C0G3R3A500NTA (EYANG) |   |  |   |
| 2000040C | CM03CG3R9C50AH (AVX)       |   |  |   |
| 2000040F | CC0201CRNP09BN3R9 (YAGE0)  | CAP, 3. 9pF±0. 25pF, 50V, 0201                | C218, C221                                     | 2 |
| 2000040G | C0201C0G3R9C500NTA (EYANG) |   |  |   |
| 2000050C | CM03CG4R7C50AH (AVX)       |   |  |   |
| 2000050F | CC0201CRNP09BN4R7 (YAGE0)  | CAP, 4. 7pF±0. 25pF, 50V, 0201                | C236, C240                                     | 2 |
| 2000050G | C0201C0G4R7C500NTA (EYANG) |   |  |   |
| 2000053C | CM03CG5R6C50AH (AVX)       |   |  |   |
| 2000053E | 0201N5R6C500CT (WALSIN)    | CAR E & R L O OF R FOV 0001                   | 0005 0000                                      | 0 |
| 2000053F | CC0201CRNP09BN5R6 (YAGE0)  | CAP, 5. 6pF $\pm$ 0. 25pF, 50V, 0201          | C235, C239                                     | 2 |
| 2000053G | C0201C0G5R6C500NTA (EYANG) |   |  |   |
| 2000056C | CM03CG6R8C50AH (AVX)       |   |  |   |
| 2000056E | 0201N6R8C500CT (WALSIN)    | CAR C O R L O OF R FOV 0001                   | C000 C000 C044                                 | 0 |
| 2000056F | CC0201CRNP09BN6R8 (YAGE0)  | CAP, 6. $8pF \pm 0$ . $25pF$ , $50V$ , $0201$ | C229, C233, C244                               | 3 |
| 2000056G | C0201C0G6R8C500NTA (EYANG) |   |  |   |
| 2000060C | CM03CG8R2J50AH(AVX)        |   |  |   |
| 2000060F | CC0201CRNP09BN8R2 (YAGE0)  | CAP, 8. 2pF±0. 5pF, 50V, 0201                 | L235   | 1 |
| 2000060G | C0201C0G8R2C500NTA (EYANG) |   |  |   |
| 2000080C | CM03CG180J50AH(AVX)        |   |  |   |
| 2000080F | CC0201JRNP09BN180 (YAGE0)  | CAP, 18pF±5%, 50V, 0201                       | C120, C257                                     | 2 |

|          |                            | -   | ī          | Ī |
|----------|----------------------------|---|------------|---|
| 2000080G | C0201C0G180J500NTA (EYANG) |   |            |   |
| 2000085C | CM03CG220J50AH(AVX)        |   |            |   |
| 2000085F | CC0201 JRNP09BN220 (YAGE0) | CAP, 22pF±5%, 50V, 0201                             | C231, C217 | 2 |
| 2000085G | C0201C0G220J500NTA (EYANG) |   |            |   |
| 1) TAI   | YO duplexer                |   |            |   |
| 5200110A | PJ D6PE2G140P3AW-Z         | SAW-DUPLEX WCDMA Band 1<br>BAL RX; 2016,50-100      | U217       | 1 |
| 5200111A | PJ D6PE1G960P3BP-Z         | SAW-DUPLEX WCDMA Band 2<br>BAL RX; 2016, 50-100     | U227       | 1 |
| 5200112A | FAR-D5PE-881M50-P3EZ-Z     | SAW-DUPLEX WCDMA Band 5                             |            |   |
| 5200112B | PJ D5PE881M5P3EZ-Z         | BAL RX; 2016, 50-100                                | U209       | 1 |
| 5200113A | PJ D5PE942M5P3GT-Z         | SAW-DUPLEX WCDMA/LTE Band<br>8 BAL RX; 2016, 50-100 | U208       | 1 |
| 3010005D | SDCL0603Q1N0BT02           | IND, 1. 0nH± 0. 1nH, 520mA, SRF=10GHz,              | L121, L120 |   |
| 3010005E | CHQ0603T-1N0B-HU           | Q=13@500MHz, 0201                                   |            |   |
| 3010005F | TFL0603T-1N0B-S            |   |            | 2 |
| 3010005G | MGCI0603T1N0BT-LF          |   |            |   |
| 3010010D | SDCL0603Q1N5BT02           |   |            |   |
| 3010010E | CHQ0603T-1N5B-HU           | IND, 1.5nH±   |            |   |
| 3010010F | TFL0603T-1N5B-S            | 0. 1nH, 410mA, SRF=10GHz,<br>Q=13@500MHz, 0201      | L244, C269 | 2 |
| 3010010G | MGCI0603T1N5BT-LF          |   |            |   |
| 3010025D | SDCL0603Q3N0BT02           |   |            |   |
| 3010025E | CHQ0603T-3N0B-HU           | IND, 3. 0nH±  |            |   |
| 3010025F | TFL0603T-3N0B-S            | 0. 1nH, 280mA, SRF=8. 6GHz,<br>Q=13@500MHz, 0201    | C220       | 1 |
| 3010025G | MGCI0603T3N0BT-LF          | 1   |            |   |
| 3010031D | SDCL0603Q3N6BT02           |   |            |   |
| 3010031E | CHQ0603T-3N6B-HU           | IND, 3. 6nH±  |            |   |
| 3010031F | TFL0603T-3N6B-S            | 0. 1nH, 240mA, SRF=7. 7GHz,<br>Q=13@500MHz, 0201    | L118       | 1 |
| 3010031G | MGCI0603T3N6BT-LF          | 1   |            |   |
| 3010038D | SDCL0603Q4N3BT02           | IND, 4. 3nH±  |            |   |
| 3010038G | MGCI0603T4N3BT-LF          | 0. 1nH, 220mA, SRF=6. 8GHz,<br>Q=13@500MHz, 0201    |            |   |
|          | l .                        | 1   |            | l |

| 3030038B | MHQ0603W4N3ST000           |  |      |   |
|----------|----------------------------|--|------|---|
| 3030038D | SDCL0603Q4N3ST02           | 1  | L277 | 1 |
| 3030038E | CHQ0603T-4N3C-HU           | IND, 4. 3nH± 0. 3nH, 350mA, SRF=5. 5GHz,                   |      |   |
| 3030038F | TFL0603T-4N3J-S            | -Q=13@500MHz, 0201   |      |   |
| 3030038G | MGCI0603T4N3ST-LF          |  |      |   |
| 3030039B | MHQ0603W4N7ST000           |  |      |   |
| 3030039D | SDCL0603Q4N7ST02           |  |      |   |
| 3030039E | CHQ0603T-4N7C-HU           | IND, 4. 7nH±  0. 3nH, 350mA, SRF=5. 5GHz,                  | L248 | 1 |
| 3030039F | TFL0603T-4N7J-S            | Q=13@500MHz, 0201  |      |   |
| 3030039G | MGCI0603T4N7ST-LF          |  |      |   |
| 3030042B | MHQ0603W6N2ST000           |  |      |   |
| 3030042D | SDCL0603Q6N2ST02           |  |      |   |
| 3030042E | CHQ0603T-6N2C-HU           | IND, 6. 2nH± 0. 3nH, 300mA, SRF=4. 0GHz,                   | L218 | 1 |
| 3030042F | TFL0603T-6N2J-S            | -Q=13@500MHz, 0201   |      |   |
| 3030042G | MGCI0603T6N2ST-LF          |  |      |   |
| 3030053B | MHQ0603W18NJT000           |  |      |   |
| 3030053D | SDCL0603Q18NJT02           | IND 10 H   |      |   |
| 3030053E | CHQ0603T-18NH-HU           | IND, 18nH±<br>5%, 180mA, SRF=2. 4GHz,<br>Q=13@500MHz, 0201 | C155 | 1 |
| 3030053F | TFL0603T-18NJ-S            | -Q-13@300MHZ, 0201   |      |   |
| 3030053G | MGCI0603T18NJT-LF          |  |      |   |
| 2000012C | CM03CG1R8C50AH (AVX)       |  |      |   |
| 2000012E | 0201N1R8C500CT (WALSIN)    |  | 0104 |   |
| 2000012F | CC0201CRNP09BN1R8 (YAGE0)  | CAP, 1. 8pF±0. 25pF, 50V, 0201                             | C164 | 1 |
| 2000012G | C0201C0G1R8C500NTA (EYANG) |  |      |   |
| 2) Mura  | aida duplexer              |  |      |   |
| 5200095A | SAYRF1G95HQ0F0A            | SAW-DUPLEX WCDMA Band 1<br>BAL RX; 2016, 50-100            | U217 | 1 |
| 5200096A | SAYRF1G88CA0B0A            | SAW-DUPLEX WCDMA/LTE Band<br>2 BAL RX; 2016, 50-100        | U227 | 1 |
| 5200097A | SAYFH836MCC0F0A            | SAW-DUPLEX WCDMA/LTE Band 5/19 BAL RX; 2016, 50-100        | U209 | 1 |

| 5200098A | SAYFH897MHC0F0A   | SAW-DUPLEX WCDMA Band 8<br>BAL RX; 2016, 50-100              | U208       | 1 |
|----------|-------------------|--|------------|---|
| 3010005D | SDCL0603Q1N0BT02  |  |            |   |
| 3010005E | CHQ0603T-1N0B-HU  | IND, 1. 0nH±   | 1110       | 1 |
| 3010005F | TFL0603T-1N0B-S   | 0. 1nH, 520mA, SRF=10GHz,<br>Q=13@500MHz, 0201               | L118       | 1 |
| 3010005G | MGCI0603T1N0BT-LF |  |            |   |
| 3010010D | SDCL0603Q1N5BT02  |  |            |   |
| 3010010E | CHQ0603T-1N5B-HU  | IND, 1.5nH± 0.1nH, 410mA, SRF=10GHz,                         | L244       | 1 |
| 3010010F | TFL0603T-1N5B-S   | Q=13@500MHz, 0201  | L244       | 1 |
| 3010010G | MGCI0603T1N5BT-LF |  |            |   |
| 3010017D | SDCL0603Q2N2BT02  |  |            |   |
| 3010017E | CHQ0603T-2N2B-HU  | IND, 2. 2nH±   | C269, C220 | 2 |
| 3010017F | TFL0603T-2N2B-S   | 0. 1nH, 290mA, SRF=10GHz,<br>Q=13@500MHz, 0201               | 0203, 0220 | 2 |
| 3010017G | MGCI0603T2N2BT-LF |  |            |   |
| 3010031D | SDCL0603Q3N6BT02  |  | L277, L248 |   |
| 3010031E | CHQ0603T-3N6B-HU  | IND, 3. 6nH± 0. 1nH, 240mA, SRF=7. 7GHz,                     |            | 2 |
| 3010031F | TFL0603T-3N6B-S   | Q=13@500MHz, 0201  |            | 2 |
| 3010031G | MGCI0603T3N6BT-LF |  |            |   |
| 3030041B | MHQ0603W5N6ST000  |  |            |   |
| 3030041D | SDCL0603Q5N6ST02  | TND F C H  |            |   |
| 3030041E | CHQ0603T-5N6C-HU  | IND, 5. 6nH±  0. 3nH, 350mA, SRF=5. 0GHz,  Q=13@500MHz, 0201 | L218       | 1 |
| 3030041F | TFL0603T-5N6J-S   | Q-13@300MHZ, 0201  |            |   |
| 3030041G | MGCI0603T5N6ST-LF |  |            |   |
| 3030044B | MHQ0603W7N5JT000  |  |            |   |
| 3030044D | SDCL0603Q7N5JT02  | TND 7 5 W  |            |   |
| 3030044E | CHQ0603T-7N5H-HU  | IND, 7. 5nH± 5%, 250mA, SRF=3. 8GHz,                         | L276       | 1 |
| 3030044F | TFL0603T-7N5JS-S  | Q=13@500MHz, 0201  |            |   |
| 3030044G | MGCI0603T7N5JT-LF |  |            |   |
| 3030053B | MHQ0603W18NJT000  |  |            |   |

| 3030053D | SDCL0603Q18NJT02           | TND 10 H  |            |   |
|----------|----------------------------|---|------------|---|
| 3030053E | CHQ0603T-18NH-HU           | IND, 18nH±<br>5%, 180mA, SRF=2.4GHz,<br>Q=13@500MHz, 0201 | C159       | 1 |
| 3030053F | TFL0603T-18NJ-S            | Q-13⊌300MHZ, 0201   |            |   |
| 3030053G | MGC10603T18NJT-LF          |   |            |   |
| 2000085C | CM03CG220J50AH (AVX)       |   |            |   |
| 2000085F | CC0201 JRNP09BN220 (YAGE0) | CAP, $22pF \pm 5\%$ , $50V$ , $0201$                      | L120, L121 | 2 |
| 2000085G | C0201C0G220J500NTA (EYANG) |   |            |   |