AcSiP Technology Corporation 3F,-1 No.207, Fusing Rd., Taoyuan City, Taoyuan County 33066 Taiwan

Date: September 12, 2016

Declaration

We, **AcSiP Technology Corporation**, declare that the device, **FCC ID: 2ADWC-AI7687H**, does not support any non-US channels in all the operational mode(s). All non-US frequencies, US 2.4G channel 12-13 and Country code selection are disabled through proprietary software and are not user changeable.

Should you have any question or comment regarding this matter, please do not hesitate to contact me.

Sincerely yours,

Sam Hus / Director

AcSiP Technology Corporation

Sull 3

Tel: +886 3 286 8388 Fax: +886 3 347 5000

E-mail: DCC@acsip.com.tw