AcSiP Technology Corporation

3F,-1 No.207, Fusing Rd., Taoyuan City, Taoyuan County 33066, Taiwan

Date: December 30, 2014

Subject: Ad Hoc Mode Function Declaration

To Whom it may concern,

We, **AcSiP Technology Corporation** declare that the device does not support any non-US channels and country code selection in all the operational mode(s) for the following product.

FCC ID: 2ADWC-AI7681H

Regards,

Sam Hus / Director

AcSiP Technology Corporation

TEL.: +886 3 286 8388 FAX:+886 3 347 5000

E-mail: samhsu@acsip.com.tw