Telecell Mobile (H.K) Ltd.

RM 801 Metro Ctr II, 21 Lam Hing Street, Kln Bay, Hong Kong

TEL:+852-27599963 FAX: +852-27599711

Email: regina@telecellmobile.com

Attestation Letter

2016-11-28

To:

FEDERAL COMMUNICATIONS COMMISSIONS
Authorization and Evaluation Division

7435 Oakland Mills Road

Columbia, MD 21046

Dear Sir or Madam:

The RF chip, model MT6625, which installed in our product Mobile Phone, model: M50L, FCC ID: 2ADX3M50L supports 5G Wi-Fi function. For use in USA, this chip will not support/enable the 5G Wi-Fi function. The 5G Wi-Fi function has been shielded by the manufacturer using the software.

Best Regards,

Signature:

Regina Wong Product Manager