Telecell Mobile (H.K) Ltd.

RM 801 Metro Ctr II, 21 Lam Hing Street, Kln Bay, Hong Kong Tel: +852 27599962 Fax: +852 27599711 Email: regina@telecellmobile.com

Attestation Letter

2016/11/18

To: FEDERAL COMMUNICATIONS COMMISSIONS Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

Dear Sir or Madam,

The RF chip, model MT6625, installed in product Mobile Phone with FCC ID: 2ADX3X55L. For use in USA this chip will not support/enable the 5G wifi function. The 5G wifi function has been shielded by the manufacturer using the software.

Sincerely Yours,

Signature:

Regina Wong

Product Manager