

Report No.: FR4D3090C

Appendix C. Setup Photographs

<Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ADZ9-JR-01-W Page Number : C1 of C2
Report Issued Date : Feb. 03, 2015
Report Version : Rev. 01


Report Template No.: BU5-FR15CWL Version 1.0




Report No.: FR4D3090C

<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ADZ9-JR-01-W Page Number : C2 of C2
Report Issued Date : Feb. 03, 2015
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.0