



Appendix A. Test Photos


1. Photographs of Conducted Emissions Test Configuration

Mode3



Report No.: FR541008-01

Front view



Rear view

SPORTON INTERNATIONAL INC. Page No. : A1 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01





Report No. : FR541008-01




Side view

SPORTON INTERNATIONAL INC. Page No. : A2 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01



FCC Test Report Report No. : FR541008-01

2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



FRONT VIEW



REAR VIEW


SPORTON INTERNATIONAL INC. Page No. : A3 of A5 TEL: 886-3-327-3456 Report Version : Rev. 01






For radiated emissions 30MHz~1GHz

Mode3



Report No.: FR541008-01

Front view



Rear view

SPORTON INTERNATIONAL INC. Page No. : A4 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01





Report No.: FR541008-01

For radiated emissions above 1GHz

Mode1



Front view



Rear view

SPORTON INTERNATIONAL INC. Page No. : A5 of A5 TEL: 886-3-327-3456 Report Version : Rev. 01