

## Annex 2: Internal photographs to PARTIAL TEST REPORT

No.: 6-0658-15-5-4a/b

According to: FCC Regulations Part 15.207 / 15.209 Part 15.247


IC-Regulations RSS-Gen, Issue 4 RSS-247, Issue 1

for

Jaguar Land Rover Ltd.

ISC1.0 Infotainment Slave Controller (Bluetooth 2.4GHz)

FCC ID: 2AE51-ISC10
IC: 2145A-ISC10
PMN: Infotainment System
HVIN: ISC1.0



Laboratory Radio Communications & Electromagnetic Compatibility Im Teelbruch 116 • 45219 Essen • Germany Registered in Essen, Germany, Reg. No.: HRB Essen 8984 Tel.: + 49 (0) 20 54 / 95 19-954 • Fax: + 49 (0) 20 54 / 95 19-964 E-mail: info@cetecom.com • Internet: www.cetecom.com



		ı	O		4	4
1 9	nı	Δ	Λt	con	ton	te
1 a	.,,		W	CUII		LO

1. INTERNAL PHOTOGRAPHS ......3



## 1. Internal photographs

