

Annex 3: External photographs to TEST REPORT

No.: 6-0658-15-5-3a

According to: FCC Regulations
Part 15.107, Part 15.109

IC-Regulations RSS-Gen, Issue 4

for

Jaguar Land Rover Ltd.

ISC1.0 Infotainment Slave Controller

FCC ID: 2AE51-ISC10
IC: 2145A-ISC10
PMN: Infotainment System

WIN: Infotainment System HVIN: ISC1.0






Table of contents

1.	EXTI	ERNAL.	PHOTO)GRA	PHS	3

1.1. EUT	3
1.2. Auxiliary Equipment	 6



1. External photographs

1.1. EUT




EUT top side




EUT buttom side





EUT connector side



EUT fan side





FW93-11E020-AF



FCC ID: 2AE51-ISC10 IC: 2145A-ISC10




This device complies with Part 15 of the FCC Rules and with Industry Canada licence-exempt RSS standard(s). Operation is subject to the following two conditions: (1)this device may not cause harmful interference, and (2)this device must accept any interference received, including interference that may cause undesired operation.

TRA
REGISTERED No:
nnnnnn
DEALER No:
xxxxxxxxxx



xxxxx/\$DPPI/2015 xxxxx





KCC-xxx-xxx-ISC1.0

NCA APROVED: ?????

AGREE PAR L'ANRT MAROC Numéro d'agrément: MR XXXX ANRT YEAR Date d'agrément: DD/MM/YYYY

ANATEL:2263-xx-xxxx

Jaguar Land Rover Ltd. Model Name:

ISC1.0











ISC Assy ISC Std

FW93-11E020-AF





7 612 053 079

20150707B

815 GHJ4B3079 F 0000001


MADE IN PORTUGAL

Label of type






BT/WLAN Antenna



BT/WLAN Antenna without housing #1






BT/WLAN Antenna without housing #2




10" Rear display front view





10" Rear display backside view



Display cable with ferrite near display