


Setup Photographs

<Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AE6S-0948 Page Number : 1 of 3
Report Issued Date : Jun. 08, 2016
Report Version : Rev. 01


Report No.: FR632203-01A

Report Template No.: BU5-FR15CBT Version 1.1





Rear View



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AE6S-0948 Page Number : 2 of 3
Report Issued Date : Jun. 08, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 1.1



<Radiated Emission>

X Plane

LF







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AE6S-0948 Page Number : 3 of 3
Report Issued Date : Jun. 08, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 1.1

Report No.: FR632203-01A