
Setup Photographs

<Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AE6S-0948 Page Number : 1 of 3
Report Issued Date : Jun. 08, 2016
Report Version : Rev. 01

Report No. : FR632203-01B

Report Template No.: BU5-FR15CBT4.0 Version 1.3





Rear View



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AE6S-0948 Page Number : 2 of 3
Report Issued Date : Jun. 08, 2016
Report Version : Rev. 01

Report No. : FR632203-01B

Report Template No.: BU5-FR15CBT4.0 Version 1.3

<Radiated Emission>

X Plane

LF



ΗF



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AE6S-0948 Page Number : 3 of 3
Report Issued Date : Jun. 08, 2016
Report Version : Rev. 01

Report No. : FR632203-01B

Report Template No.: BU5-FR15CBT4.0 Version 1.3