

Appendix A. Test Photos

Report No. : FR540713-01

SPORTON INTERNATIONAL INC. Page No. : A1 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01





1 Photographs of Conducted Emissions Test Configuration



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A2 of A7

Report Version

: Rev. 01

Report No.: FR540713-01



Report No. : FR540713-01



SIDE VIEW


SPORTON INTERNATIONAL INC. Page No. : A3 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01






2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



Report No. : FR540713-01

FRONT VIEW



REAR VIEW


SPORTON INTERNATIONAL INC. Page No. : A4 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01




FCC Test Report

Report No. : FR540713-01

For radiated emissions 30MHz~1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A7

Report Version

: Rev. 01




FCC Test Report

Report No. : FR540713-01


: A6 of A7

: Rev. 01

For radiated emissions above 1GHz



FRONT VIEW




REAR VIEW

SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version





Report No. : FR540713-01



EUT take a close-up



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A7 of A7

Report Version :

: Rev. 01