

P.O. BOX 841543

Houston, TX 77284

Tel. +1-832-316-7770

## Tune Up Procedure

Federal Communications Commission Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

Houston, February 25th, 2015

Re: Tune Up Procedure for FCC ID: 2AEAL-SB-850-1900

To Whom It May Concern:

There are no external tuning and/or other adjustments. Each booster is factory set to not exceed maximum gains and power levels as proved in test results.

Sincerely Yours,

Sabino R. Leone, General Manager/Engineering

Wireless Engineering Ltd Co.