


Internal photos





Test Report Number: 18071039HKG-001, 18071039HKG-002 FCC ID: 2AEFK-SCD730

Internal photos






Test Report Number: 18071039HKG-001, 18071039HKG-002 FCC ID: 2AEFK-SCD730

Internal photos






Test Report Number: 18071039HKG-001, 18071039HKG-002 FCC ID: 2AEFK-SCD730


Internal photos






Test Report Number: 18071039HKG-001, 18071039HKG-002 FCC ID: 2AEFK-SCD730


Internal photos






Test Report Number: 18071039HKG-001, 18071039HKG-002 FCC ID: 2AEFK-SCD730


Internal photos






Test Report Number: 18071039HKG-001, 18071039HKG-002 FCC ID: 2AEFK-SCD730

Internal photos





Test Report Number: 18071039HKG-001, 18071039HKG-002 FCC ID: 2AEFK-SCD730


Internal photos





Test Report Number: 18071039HKG-001, 18071039HKG-002 FCC ID: 2AEFK-SCD730

Internal photos



Test Report Number: 18071039HKG-001, 18071039HKG-002 FCC ID: 2AEFK-SCD730