US Tech Test Report: FCC ID: Test Report Number: Issue Date: Customer: Model:

FCC Part 15.249 2AEFO-GZFUSION1 15-0106 April 14, 2015 Gozio, Inc Fusion Beacon 1.0

## **INTERNAL PHOTOGRAPHS**



Figure 1. PCB, Component Side

US Tech Test Report: FCC ID: Test Report Number: Issue Date: Customer: Model:

FCC Part 15.249 2AEFO-GZFUSION1 15-0106 April 14, 2015 Gozio, Inc Fusion Beacon 1.0




Figure 2. PCB, Back Side