




Appendix A. Test Photos

1. Photographs of Conducted Emissions Test Configuration



**Report No. : FR531824** 

Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A1 of A6

Report Version : Rev. 01



FCC Test Report No.: FR531824



Side view


SPORTON INTERNATIONAL INC. Page No. : A2 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973




FCC Test Report **Report No. : FR531824** 

## 2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A3 of A6 TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973






Report No. : FR531824

For radiated emissions 30MHz~1GHz



Front view



Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A6 Report Version : Rev. 01




FCC Test Report

Report No. : FR531824

## For radiated emissions above 1GHz



Front view




Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A6
Report Version : Rev. 01



Report No.: FR531824



EUT took a close view

SPORTON INTERNATIONAL INC. Page No. : A6 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973