


FCC Test Report **Report No. : FR540138**

Appendix A. Test Photos



Front view



: A1 of A5

: Rev. 01

Rear view

SPORTON INTERNATIONAL INC. Page No. TEL: 886-3-327-3456 Report Version







Report No. : FR540138


Side view

SPORTON INTERNATIONAL INC. Page No. : A2 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01




FCC Test Report **Report No. : FR540138**

2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



Front view



Rear view

SPORTON INTERNATIONAL INC. Page No. : A3 of A5 TEL: 886-3-327-3456 Report Version : Rev. 01




FCC Test Report


Report No. : FR540138

For radiated emissions 30MHz~1GHz

Mode 1



Front view



Rear view

SPORTON INTERNATIONAL INC. Page No. : A4 of A5 TEL: 886-3-327-3456 Report Version : Rev. 01



FCC Test Report


Report No. : FR540138

For radiated emissions above 1GHz

Mode 1



Front view



Rear view

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973

Page No. : A5 of A5

Report Version : Rev. 01