

Report No.: FR552245-01

Appendix A. Setup Photographs

<Conducted Emission>



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AEHI-EL0215

: A1 of A2 Page Number Report Issued Date : Jul. 22, 2015 : Rev. 01 Report Version


Report Template No.: BU5-FR15CWPC Version 1.0




Report No.: FR552245-01

<Radiated Emission>

Frequency: 9 kHz to 30 MHz



Frequency: 30 MHz to 1000 MHz



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AEHI-EL0215 Page Number : A2 of A2
Report Issued Date : Jul. 22, 2015
Report Version : Rev. 01

Report Template No.: BU5-FR15CWPC Version 1.0