

Appendix D. Setup Photographs

<Conducted Emission>

Mode 2



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AEHJSRU532 Page Number : D1 of D3
Report Issued Date : May 11, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.2


Report No. : FR610515




<Radiated Emission>

Ant. 1

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AEHJSRU532 Page Number : D2 of D3
Report Issued Date : May 11, 2016
Report Version : Rev. 01

Report No.: FR610515

Report Template No.: BU5-FR15CBT4.0 Version 1.2




Report No.: FR610515

Ant. 2

LF







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AEHJSRU532 Page Number : D3 of D3
Report Issued Date : May 11, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.2