Appendix E. Setup Photographs

<Conducted Emission> Mode 2



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AEHJSRU532 Page Number : E1 of E3
Report Issued Date : May 09, 2016
Report Version : Rev. 01

Report No.: FR610515B


Report Template No.: BU5-FR15CANT Version 1.0



<Radiated Emission>

Antenna 1

<LF>



<HF>



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AEHJSRU532 Page Number : E2 of E3
Report Issued Date : May 09, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CANT Version 1.0




Antenna 2

<LF>



<HF>



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AEHJSRU532 Page Number : E3 of E3
Report Issued Date : May 09, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CANT Version 1.0