

Appendix A. Setup Photographs

<Conducted Emission>



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AEJC-PIQ1 Page Number : A1 of A2
Report Issued Date : Sep. 09, 2015
Report Version : Rev. 01

Report No.: FR541402B


Report Template No.: BU5-FR15CNFC Version 1.0




Report No. : FR541402B

<Radiated Emission>

9kHz~30MHz



30MHz~1GHz



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AEJC-PIQ1 Page Number : A2 of A2
Report Issued Date : Sep. 09, 2015
Report Version : Rev. 01

Report Template No.: BU5-FR15CNFC Version 1.0