



Report No. : FR7N2922-02

Appendix A. Test Photos

1. Photographs of Conducted Emissions Test Configuration



Front view



: A1 of A4

: Rev. 01

Side view

SPORTON INTERNATIONAL INC. Page No. TEL: 886-3-327-3456 Report Version

FAX: 886-3-327-0973







Report No. : FR7N2922-02

Under table view

SPORTON INTERNATIONAL INC. Page No. : A2 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01


FAX: 886-3-327-0973




FCC Test Report

Report No.: FR7N2922-02

2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



Front view



: A3 of A4

: Rev. 01

Rear view

SPORTON INTERNATIONAL INC. Page No. Report Version TEL: 886-3-327-3456


FAX: 886-3-327-0973



FCC Test Report

Report No. : FR7N2922-02

For radiated emissions 30MHz~1GHz



Front view



Rear view

 ${\tt SPORTON\ INTERNATIONAL\ INC.}$

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A4 Report Version : Rev. 01