Test report No. : 11184500H-A-R1
Page : 34 of 36
Issued date : March 28, 2016
Revised date : March 31, 2016
FCC ID : 2AEMXY7011A00000

# **APPENDIX 3: Photographs of test setup**

# **Conducted Emission**




Photo 1




Photo 2

# UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 11184500H-A-R1
Page : 35 of 36
Issued date : March 28, 2016
Revised date : March 31, 2016
FCC ID : 2AEMXY7011A00000

### **Radiated Spurious Emission**




Photo 1




Photo 2


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124


Test report No. : 11184500H-A-R1
Page : 36 of 36
Issued date : March 28, 2016
Revised date : March 31, 2016
FCC ID : 2AEMXY7011A00000

#### Worst Case Position (Horizontal: X-axis/ Vertical: Z-axis)


#### X-axis



Y-axis



**Z**-axis



**End of Report** 

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124