Setup Photographs

<Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AET6-0610 Page Number : 1 of 4
Report Issued Date : Jan. 21, 2016
Report Version : Rev. 02

Report No.: FR552738-01C

Report Template No.: BU5-FR15CWL Version 1.0

<Radiated Emission>

Z Plane for Ant. 2

LF







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AET6-0610 Page Number : 2 of 4
Report Issued Date : Jan. 21, 2016
Report Version : Rev. 02

Report Template No.: BU5-FR15CWL Version 1.0


Report No.: FR552738-01C

Y Plane for Ant. 1

LF



HF




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AET6-0610 Page Number : 3 of 4
Report Issued Date : Jan. 21, 2016
Report Version : Rev. 02

Report Template No.: BU5-FR15CWL Version 1.0


Report No.: FR552738-01C

Y Plane for Ant. 2 (EUT with Base)

LF



HE



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AET6-0610 Page Number : 4 of 4
Report Issued Date : Jan. 21, 2016
Report Version : Rev. 02

Report No.: FR552738-01C

Report Template No.: BU5-FR15CWL Version 1.0